

ELGRO PTE LTD

IMATE*

SHA2879T

21/04/21

CHIANG/ABC

IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH /LH		\$111.60
10	REAR BUMPER CLIPS		\$22.00
1	REAR BUMPER REINFORCEMENT		\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH		\$276.20
1	REAR BUMPER LOWER MOULDING		\$155.00
1	REAR BUMPER FOG LAMP		\$201.50
2	NUMBER PLATE LAMP		\$85.30
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	EMBLEM- IONIQ		\$31.30
1	BOOT LID HYBRID PLATE		\$24.30
1	BOOTLID H EMBLEM		\$28.00
1	REAR BUMPER REFLECTOR RH/ LH		\$82.90
1	REAR FLOOR UNDER		\$225.00
1	SMART KEY ANTENNA		\$40.50
1	REAR BUMPER TOW COVER		\$98.80
	SUB TOTAL		\$2,773.15
	20.00% DISCOUNTED TOTAL		\$554.63
			\$2,218.52
1	REAR NUMBER PLATE/W HOLDER		\$50.00
1	REAR REVERSE SENSOR		\$180.00
1	COMFORT LOGO STICKER		\$30.00
1	COMFORT APP STICKER		\$40.00
1	TEL NUMBER STICKER		\$30.00
			\$330.00
			\$850.00
			\$600.00
			\$60.00
			\$60.00
			\$60.00
			\$1,630.00
	ESTIMATE TOTAL		\$4,178.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charge

Panel Beating

Spray Painting Charge

Check wiring

Tuff Kote

Remove/refix Reverse sensor

Towing - \$60

TOTAL LABOUR

1145

\$1,630.00**ESTIMATE TOTAL**

\$3372.48

\$4,178.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanghin 97495749

WP' 23/4/21 E 1345

P/P Resurvey before paint

Tanghin 01/04/21

2-3 days