

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 8603G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BUCKLED	709.10	709.10
2	REAR BUMPER REVERSE SENSORS (CONSISTENT)	SCRATCHED (1 PCS ONLY)	453.80	226.90
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	40.00	40.00
2	REAR BUMPER SIDE RETAINER (CONSISTENT)	N/S DISTORTED	35.00	17.50
1	REAR BUMPER INNER REINFORCEMENT (CONSISTENT)	* CHECK	188.60	-
1	LH TAILLAMP (CONSISTENT)	* CHECK	295.80	-
1	REAR BOOT LID (CONSISTENT)	TO REPAIR SEE LABOUR	878.10	-
1	REAR BOOT CENTRE 'H' LOGO (CONSISTENT)	NOT NECESSARY	32.10	-
1	REAR BOOT LH 'ACCORD' EMBLEM (CONSISTENT)	NOT NECESSARY	19.20	-
1	REAR BOOT LH REFLECTOR /LAMP (CONSISTENT)	SERVICEABLE	140.30	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	85.00	-
1	REAR END PANEL (CONSISTENT)	* CHECK	387.80	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	* CHECK	97.70	-
	LESS 20% DISCOUNT		-672.50	-198.70
			2,690.00	794.80
	SPECIAL NETT ITEMS			
1	SET REAR END PANEL SEALANT (SN)(CONSISTENT)	* CHECK	50.00	-
			50.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES.	* CHECK	900.00	-
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		1,000.00	400.00
	TO CHECK WIRING & LIGHTINGS.		40.00	20.00
	TO REMOVE,REFIT AND RESET REVERSE SENSORS.		80.00	60.00
	TO REMOVE, REFIT REAR UPHOLSTERY AND ATTACHMENTS.		120.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	* CHECK	80.00	-
			2,220.00	540.00
	GRAND TOTAL		4,960.00	1,334.80

Report Ref No. CC4/ASM21005060/Kga3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,725.92 NETT)			1,334.80
-----------------------------------------------------------------------------------------------------	--	--	----------

Report Ref No. CC4/ASM21005060/Kga3q2

KONG SENG CHEONG

Licensed Appraiser