

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No. 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJK8603G

4 days

Not Authorised
L1 Rep &
Running After Party

No.	Qty	List Items	
1	1	Rear bumper	\$ Bu 709.10 ✓
2	1/2	Rear bumper reverse sensors	\$ fur 453.80 ✓
3	1 set	Rear bumper clips	\$ fu 40.00 ✓
4	2	Rear bumper side retainer	MS \$ 35.00 ✓
5	1	Rear bumper inner reinforcement	\$ 188.60 ?
6	1	LH taillamp	\$ 295.80 ?
7	1	Rear boot lid	\$ 878.10 X
8	1	Rear boot centre "H" logo	\$ 32.10 X
9	1	Rear boot LH "ACCORD" emblem	\$ 19.20 X
10	1	Rear boot LH reflector/lamp	\$ 140.30 X
11	1	Rear boot weatherstrip	\$ 85.00 X
12	1	Rear end panel	\$ 387.80 ?
13	1	Rear end panel top garnish	\$ 97.70 ?
			\$ 3,362.50
			Less 20% \$ 672.50
			Total : \$ 2,690.00

Special Nett Items

14	1 set	Rear end panel sealant	\$ 50.00 ?
----	-------	------------------------	------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	900.00	?
2	To putty and spray Spray Paintings charges.	\$	1,000.00	400
3	To check wiring & lightings	\$	40.00	20
4	To remove, refit and reset reverse sensors.	\$	80.00	60
5	To remove, refit rear upholstery and attachments.	\$	120.00	60
6	To supply and apply anti rust treatment	\$	80.00	?
	Total :	\$	2,220.00	

Total Parts and Labour : \$ 4,960.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: