



PRIORITY SERVICES

INSURANCE LOSS ADJUSTERS AND MOTOR APPRAISERS

Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel: 6293 4822 Fax: 6296 3283

VEHICLE DAMAGE INSPECTION REPORT

Our File No: TP-0167/11/18
Date: 12/12/2018

REFERENCE

Handling Insurer: Sompoo Insurance Singapore Pte. Ltd. Policy No: D17MTPV01008349
Claimant Vehicle No: ET128B Insured Vehicle No: SLE2634P
Date of Loss: 14/11/2018 Nature of Claim: TP Claim No: CMTD1805022

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **ET128B**
Make & Model: BMW 335i, 3.0 (A) Engine No: N54B30A05816979
Reg. Date: 11/08/2009 (Man. Year: 2008) Chassis No: WBAWL72030PZ84515
Colour: Metallic Silver Odometer: 148987 km
Engine Capacity: 2979 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 235/40/ZR15 Rear Tyre Size: 235/40/ZR15
Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/11/2018
Date Inspected: 19/11/2018 Inspected At: Yap Lee Motor (HQ)
1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 0.0 days

Adjuster: Lawrence Ng
Surveyor
Manager: Sharon Kho
Administrator

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PRE-REPAIR SURVEY

Date of Accident : 14-Nov-2018

Date and Time of Request : 19-Nov-2018 / 11.29am

Date and Time of Inspection : 1) 19-Nov-2018 / 12.30pm

2) 20-Nov-2018 / 9.45am (For dismantled items)

3) 28-Nov-2018 / 9.00am (For after repair)

DOCUMENTS AVAILABLE AT TIME OF INSPECTION

1)T/P ET 128 B Singapore Accident Statement & Accident Photos

2)O/I SLE 2634 P Singapore Accident Statement & Accident Photos

VISUAL DAMAGES

At the front RH portion. (RH front road wheel was also affected)

Damages subject to consistency.

REMARKS

Despite our request, the repairer would not provide: -

1) Repairer estimate

Pre-Accident market value: About \$45,000.00.

PARF/COE Rebate: \$32,976.00 (COE expiry on 10-Aug-2019).

Estimated repair cost: About \$2,000.00.

Estimated period of repairs: About 3 working days.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Dec 2018)	
Parts:	N/A	BMW 335I 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Priority Services/ET128B/12/12/2018 13:57	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Priority Services/ET128B/12/12/2018 13:57 . Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Priority Services/ET128B/12/12/2018 13:57 . Not valid without Reference section.

< END OF ESTIMATES >