



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

INVOICE

Ms Jacqueline Chen
35 Chu Lin Road
Singapore 669929

Invoice No. : HA/1812-27

Date : 10/12/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 526.00
SGD Dollar : Five Hundred Twenty Six Dollars Only.	
Our Reference : PAS/TP/0461118	
Vehicle No. : ET128B	
Make & Model : BMW 335i (A)	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "**PROMINENT APPRAISER SERVICES PTE LTD**".

Please indicate our "**INVOICE NO.**" on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.

For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0461118

Date of Report : 10/12/2018

To : Ms Jacqueline Chen
35 Chu Lin Road
Singapore 669929

Date of Assignment : 19/11/2018
Report requested by : Ms Jacqueline Chen
Date of Accident : 14/11/2018
Date of Inspection : 19/11/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : ET128B
Make & Model : BMW 335i (A)
Date of Registration : 11/08/2009
Colour : Met. Silver

Engine Capacity (cc) : 2979cc
Mileage (km) : 148987km
Chassis / Frame No. : WBAWL72030PZ84515
Engine No. : N54B30A05816979

TYRE CONDITION

Front LH : 6 mm
Make : Michelin

Front RH : 6 mm
Make : Michelin

Rear LH : 6 mm
Make : Michelin

Rear RH : 6 mm
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Yap Lee Motor
1, Kaki Bukit Ave 6, Blk B, #01-26, Autobay @ Kaki Bukit, Singapore 417883

ASSESSMENT

Repairer's Estimate : \$ 11,718.05
Revised Amount : \$ 9,927.15
Less Excess : \$ -
Recommended Reserve : \$ 7,940.00 (Lump Sum)

Estimated Normal Period of Repairs : 5 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : ET128B

Report No. : PAS/TP/0461118

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Yap Lee Motor, 1, Kaki Bukit Ave 6, Blk B, #01-26, Autobay @ Kaki Bukit, Singapore 417883.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the RHF portion. (The RHF roadwheel was also affected)

DAMAGES

The RH headlamp, front bumper, RHF fender, RHF sport rim, RHF carrier, RHF suspension, RHF adius rod, RHF wishbone, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$9,927.15.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$7,940.00.

This inspection was conducted entirely on a '**Without Prejudice**' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd

Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : ET128B

Report No. : PAS/TP/0461118

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Headlamp (Bi-xenon) RH	Cracked	\$ 2,495.00	\$ 2,495.00
2	1 pc	Headlamp bracket RH	Cracked	\$ 81.00	\$ 81.00
3	1 pc	Frt bumper (M/sport)	Dented/Deformed	\$ 1,351.00	\$ 1,351.00
4	1 pc	Frt bumper fog lamp RH	Refit	\$ 287.00	\$ -
5	1 pc	Frt bumper fog lamp bracket RH	Cracked	\$ 62.00	\$ 62.00
6	1 pc	Frt fender RH	Dented/Repair	\$ 757.00	\$ -
7	1 pc	Frt fender cowling RH	Torn/Deformed	\$ 149.00	\$ 149.00
8	1 pc	Frt sport rim RH (ET:34, M/sport)	Dented/Defaced	\$ 965.00	\$ 965.00
9	1 pc	Frt wheel hub assy RH	Warped/Distorted	\$ 489.00	\$ 489.00
10	1 pc	Frt carrier RH	Bent/Distorted	\$ 449.00	\$ 449.00
11	1 pc	Frt adius rod RH	Bent	\$ 229.00	\$ 229.00
12	1 pc	Frt wishbone RH	Bent	\$ 225.00	\$ 225.00
13	1 pc	Frt stabilizer bar	Refit	\$ 378.00	\$ -
14	1 pc	Frt stabilizer link RH	Bent	\$ 102.00	\$ 102.00
15	1 pc	Frt fender RH	Dented/Repair		(Refer labour no. 4 & 5)
				\$ 8,019.00	\$ 6,597.00
				Less Discount : 5%	5% \$ 329.85
				List Parts Sub-Total :	\$ 7,618.05
1	1 pc	Frt tyre RH (Depreciate 20%)	Cut	S/N \$ 450.00	\$ 360.00
2	1 set	Frt suspension coilover	RH Bent/Broken	S/N \$ 1,400.00	\$ 1,400.00
3	1 bot	Brake fluid	Necessary	S/N \$ 20.00	\$ 20.00
4	1 set	Frt bumper side skirt (CF)	RH Cracked	S/N \$ 600.00	\$ 600.00
				Special Nett Sub-Total :	\$ 2,470.00
				Parts Total :	\$ 10,088.05
					\$ 8,647.15



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : ET128B

Report No. : PAS/TP/0461118

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check electrical system and calibrate/focus headlamp.	\$ 60.00	\$ 50.00
2	To remove, check and replace RHF undercarriage parts. (Include flush and bleed brakes system)	\$ 250.00	\$ 220.00
3	To conduct wheel alignment (2x).	\$ 120.00	\$ 120.00
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 600.00	\$ 440.00
5	To spray painting, blending on affected and adjacent area.	\$ 600.00	\$ 450.00
Labour Total :		<u>\$ 1,630.00</u>	<u>\$ 1,280.00</u>
Total (Parts & Labour) :		<u>\$ 11,718.05</u>	<u>\$ 9,927.15</u>

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 7,940.00

Under normal circumstances, the repairs should be completed within a reasonable period

of **5 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

56 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.