

ASS. REC. BY:

REF:

LPC/21003067/KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

HC

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Smk 5039U

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c.

1496

Colour

M. Silver

AC:

Insured / Std / NI / NA

Sp. Reading

183781

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7

2005109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F: Rapid 185/60R15

R: M220

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

22/4/21

D.O.I.

26/4/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1) GIA not ready

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 22 / 04 / 2021

ESTIMATE COSTS OF REPAIR

M/s JW Leasing Pte Ltd

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SMK 5039 U - Honda Shuttle Hybrid 1.5

Accident date : 22 / 04 / 2021

*Not Authorised
11 Days @
Repair After Paim
5 days*

Quantity	Descriptions	Amount (S\$)	
1	1 pc tail gate	\$ 1,193.00	✓
2	1 pc tail gate Honda Logo	\$ 38.00	—
3	1 pc tail gate 'SHUTTLE' emblem	\$ 55.00	—
4	1 pc tail gate "Hybrid" emblem	\$ 75.50	✓
5	1 pc tail gate chorme	\$ 189.50	X
6	1 pc tail gate weather strip	\$ 168.50	
7	1 pc tail gate inner lock	\$ 180.00	X
8	2 pcs tail gate hinge 1 @ 50.00	\$ 100.00	X
9	2 pcs tail gate damper 1 @ 165.40	\$ 330.80	X
10	1 pc tail gate inner trim board	\$ 320.40	✓
11	2 pcs tail gate reflector 1 @ 395.20	\$ 790.40	X
12	2 pcs tail lamp 1 @ 550.40	\$ 1,100.80	X
13	1 pc rear bumper fascia	\$ 1,200.00	✓
14	2 pcs rear bumper side retainer 1 @ 42.50	\$ 85.00	X
15	2 pcs rear bumper bracket 1 @ 42.50	\$ 85.00	X
16	2 pcs rear bumper sponge 1 @ 169.00	\$ 338.00	?
17	1 pc n/s rear bumper lower side garnish	\$ 189.50	X
18	2 pcs rear bumper reflector 1 @ 86.40	\$ 172.80	X
19	2 pcs rear bumper reflector garnish 1 @ 45.90	\$ 91.80	X
20	1 pc rear bumper tow cover	\$ 26.50	X
21	2 pcs rear fender inner garnish 1 @ 489.60	\$ 979.20	?
22	1 pc rear windscreen glass molding	\$ 149.20	✓
23	1 pc rear end panel inner garnish	\$ 155.50	✓
24	1 pc rear end panel	\$ 685.00	—
25	1 pc rear spare tyre board	\$ 655.40	X
		\$ 9,354.80	
		\$ 1,870.96	
		\$ 7,483.84	

Less 20%

Balance C/FD

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SMK 5039 U)

\$ 7,483.84

26	1 pc	rear no. plate
27	1 set	rear bumper reverse sensor
28	1 pc	rear panel inner seal
29	1 pc	rear windscreen inner seal
30	1 pc	rear windscreen inner gum

\$	100.00	sn X
\$	350.00	sn 2001n
\$	250.00	sn 301n
\$	60.00	sn 301n
\$	60.00	sn 401n
\$	8,303.84	

Labour charges

\$ 1,800.00 6001

To putty and spray painting

\$ 1,600.00 6001

To check, repair wiring

\$ 120.00 201

Re-seal anti rust

\$ 120.00 601

Remove and refix cushion seat, garnish, carpet

\$ 350.00 601

To transfer tail gate

\$ 120.00 601

Remove and refix reverse sensor

\$ 120.00 501

Remove and refix rear windscreen glass

\$ 160.00 1201

\$ 12,693.84

Plus : GST 7%

\$ 888.57

Sub-total

\$ 13,582.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: