



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21005067/Kvf3e2 Date: 17/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMV 1390Y	Veh. Inspected	SMK 5039U
	Policy No.		Coverage (\$)	0.00
	Claim No.	20/21/21/VP00/024481	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	23/04/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72005109	Colour	METALLIC SILVER
	Odometer	183781 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	RAPID	7 mm
	L/H Front Tyre	185/60 R15	RAPID	7 mm
	R/H Rear Tyre	185/60 R15	MOZZO	8 mm
	L/H Rear Tyre	185/60 R15	MOZZO	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/04/2021	Inspection Date	26/04/2021
	Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	