

Your Ref: IN.515465.E(W)

Date: 18th Oct 2021

Our Ref: CS1/LAW21005071/Duf3e2

M/s Riaz LLC133 New Bridge Road
#09-09 Chinatown Point
Singapore 059413

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBL 3431H
INSURED VEHICLE: SKV 2271A
ACCIDENT DATE: 06/02/2020**

We thank you for your instruction on 23/04/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBL 3431H from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by Priority Services with colour photographs.
- c) Final Repair Bill of FBL 3431H from M/s Equator Brotherhood.
- d) Singapore Accident Statement of Vehicles FBL 3431H
- e) Colour damaged vehicle photographs of FBL 3431H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBL 3431H
Make & Model	: Yamaha MT-09 ABS Tracer
Chassis Number	: JYARN29K000001056
Year of Registration	: 2016
Engine Capacity	: 847 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.