



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Date: 12 August 2020

Your Ref: CMTD2000614/THE

Our Ref: TP-0043/08/20

Motor Claims Department
M/s. Sompoo Insurance Pte. Ltd.
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

Attention: Ms. Thelma Choo

Madam,

Inspection of 2016 Yamaha MT-09 Tracer Motorcycle
Registration No.: FBL 3431 H
Odometer Reading: 66818 km
Chassis No.: JYARN29K000001056

We refer to your instructions to us to conduct a paper survey of the above vehicle. A pre-repair survey was conducted on 12-02-2020, followed by inspection of dismantled parts on 03-04-2020 and resurvey after repairs on 09-04-2020.

The following documents were received: -

- 1) Copy of survey report by M/s. Advanced Automotive Consultancy Pte Ltd
- 2) 92 copies of photos depicting damages sustained by FBL 3431 H
- 3) Accident and police reports by rider of FBL 3431 H and driver of SKV 2271 A

The vehicle sustained RH rear and LH side damages during an accident on 06-02-2020.

Repair cost submitted was \$7,600.00 lump-sum.

We append below our findings: -

<u>Replacement of Parts</u>		<u>Revised Amount</u>	<u>Our Recommendation</u>
1pc.	Yamaha front suspension – refitted	\$ 2,430.00	\$ -
1pc.	Yamaha handle bar – refitted	252.00	-
2pcs.	Yamaha headlight panel (carbon fibre lock) – RH refitted/LH not affected	180.00	-
1pc.	Yamaha headlight (right) – not affected	315.00	-
1pc.	Yamaha headlight fairing (left)	108.00	108.00
1pc.	Yamaha rear number plate holder	72.00	72.00

1pc.	Yamaha rear number plate holder bracket – slightly bent/repairable	\$ 99.00	\$ -
1pc.	Yamaha rear number plate reflector (yellow) (right hand) – refitted	18.00	-
2pcs.	Yamaha rear signal light	117.00	117.00
1pc.	Yamaha front sprocket cover	45.00	45.00
1pc.	Yamaha rider footrest bracket (left) – refitted	135.00	-
1pc.	Yamaha rider footrest (left)	49.50	49.50
1pc.	Yamaha rider footrest pin (left)	13.50	13.50
1pc.	Yamaha rider footrest spring (left)	9.00	9.00
1pc.	Yamaha rider footrest holder (left)	13.50	13.50
1pc.	Yamaha rider footrest safety distance screw (left)	4.50	4.50
1pc.	Yamaha mirror (left)	99.00	99.00
2pcs.	Yamaha handguard cover (black) – RH not consistent	117.00	58.50
2pcs.	Yamaha handguard bracket – not affected	144.00	-
1pc.	Yamaha side pannier box bracket set	252.00	252.00
1pc.	Yamaha pillion footrest (left)	40.50	40.50
1pc.	Yamaha pillion footrest pin (left)	13.50	13.50
1pc.	Yamaha pillion footrest bearing (left)	4.50	4.50
1pc.	Yamaha gear shifter	76.50	76.50
1pc.	Yamaha rear mudguard	67.50	67.50
1pc.	Yamaha rear mudguard bracket	76.50	76.50
1pc.	Yamaha rear swing arm – not affected/refitted	1,125.00	-
1pc.	Yamaha rear swing arm bush – not necessary	162.00	-
1pc.	Yamaha front signal (left) – refitted	58.50	-
		<u>\$ 6,097.50</u>	<u>\$ 1,120.50</u>
	Less 10%	-	112.05
		<u>\$ 6,097.50</u>	<u>\$ 1,008.45</u>

Special Nett Items:-

1pc.	Denali fog light cover (yellow) – not fitted during after repairs	\$ 50.00	\$ -
1pc.	Denali fog light set – not fitted during after repairs	680.00	-
1pc.	Puig windshield (tall) – refitted	380.00	-
1pc.	Front number plate – not necessary	15.00	-
1pc.	Rear number plate	20.00	20.00
1pc.	Givi Trekker Outback box 58L – refitted	750.00	-
1pc.	Givi Trekker Outback box base – not necessary	80.00	-
1pc.	Givi Trekker Outback box rack – not affected	110.00	-
1pc.	Crash protection bar (left hand)	180.00	180.00
		<u>\$ 8,362.50</u>	<u>\$ 1,208.45</u>
	Total For Parts:-		

Labour Charges:-

To remove and replace front wheel bearing, front fork, steering cone.	\$ 180.00	\$ -
To remove and replace above body damaged parts, check wiring and lighting system.	400.00	300.00
To conduct chassis alignment.	350.00	-
To remove DID X-ring chain to assist replacement of swing arm.	180.00	-
Transportation – workshop to accident reporting center	50.00	30.00
Transportation – accident reporting center to workshop	50.00	30.00
Total:-	<u>\$ 9,572.50</u>	<u>\$ 1,568.45</u>

Lump-sum repairs: \$ 7,600.00 \$ 1,250.00

Estimated period of repairs: 4 working days

Pre-accident Market Value : About \$ 17,000.00 (At the time of accident)
COE rebate : \$ 4,136.00 (COE expiry on 04-09-2026)

Vehicle within economical limit to repair.


Economical limit to repair : About \$12,800.00

We leave the decision of settlement to you.

Assuring you of our best services always


Yours faithfully

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA
Motor Appraiser

Surveyed by:



LAWRENCE NG, MSAAA
Motor Appraiser