



陳林峰有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SGX561M

Date of Accident : 18 April 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Tok Ban Tin

Date : 21 April 2021

Estimate To Repair SKU4924S - Mercedes Benz C 180 Avantgarde (R17 LED)

Chassis No : WDD2050402R069143

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> rear bumper	\$ 1,530.00
			\$ 1,530.00
		Less 10 %	\$ 153.00
			\$ 1,377.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Putty and spray painting of the affected portion.	\$ 350.00
02		To check electrical lighting concerned.	\$ 30.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 300.00
04		To reinstall of rear bumper parking sensor.	\$ 100.00
			\$ 780.00
		Total	\$ 2,157.00