



陳林摩呀私人有限公司  
TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SGX561M

Date of Accident : 18 April 2021

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Tok Ban Tin

Date : 21 April 2021

Estimate To Repair SKU4924S - Mercedes Benz C 180 Avantgarde (R17 LED)

Chassis No : WDD2050402R069143

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> rear bumper	\$ <del>Rp</del> 1,530.00
			\$ 1,530.00
		Less 10 %	\$ 153.00
			\$ 1,377.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		Putty and spray painting of the affected portion.	\$ 250 350.00
02		To check electrical lighting concerned.	\$ X 30.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 200 300.00
04		To reinstall of rear bumper parking sensor.	\$ 30 100.00
			\$ 780.00
		Total	\$ 2,157.00

Tan Lim 9749 5749  
wp 23/4/21 @ 5pm  
2 days  
Assy after repair  
tanlim @ khian h-wm.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: