



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0343/2021/HR
DATE : 21-Apr-21
WIP : 23733

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LOH ZHI YI
ADDRESS : 28 JALAN LEMPENG
#22-04
SINGAPORE 128807
TELEPHONE : HP +65 96842846
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMU 5810 G**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 20/8/2020
ENGINE NO : CZD 897537
CHASSIS NO : WAUZZZF3XL1115087
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
DATE OF ACCIDENT : 16-Apr-21
PLACE OF LOCATION : NEAR 293 HOLLAND ROAD

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 5810 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR 'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N \$	800.00 500.	
3	TO DISMANTLE AND RENEW REAR BUMPER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	4,000.00 1500	
4	TO RESPRAY FRONT BUMPER, LHS FRONT DOOR, LHS REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLE. \$	3,000.00 1850	5 x 550 = 1650. Handle x 2 = 200
5	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 8,472.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 5810 G

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER COVER - RH <i>Regis</i>	1	\$ 1,008.00	<i>X</i>
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00	<i>X</i>
3	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	<i>X</i>
4	FRONT BUMPER GRILLE - LH / RH	2	\$ 220.00	<i>X</i>
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	<i>X</i>
6	FRONT RADIATOR GRILLE	1	\$ 1,433.00	<i>X</i>
7	FRONT RADIATOR STRIKER PLATE	1	\$ 244.00	<i>X</i>
8	FRONT DOOR - LH <i>Dented</i>	1	\$ 2,805.00	<i>✓</i>
9	FRONT DOOR OUTER DOOR SEAL - LH <i>Not</i>	1	\$ 166.00	<i>✓</i>
10	FRONT DOOR ATTACHMEN PATS - LH <i>Not</i>	1	\$ 157.00	<i>X</i>
11	FRONT DOOR CATCH	1	\$ 120.00	<i>?</i>
12	FRONT DOOR COVER - LH <i>Dented</i>	1	\$ 268.00	<i>✓</i>
13	SIDE MIRROR - LH <i>Not</i>	1	\$ 2,065.00	<i>✓</i>
14	SIDE MIRROR CAP - LH <i>Not</i>	1	\$ 191.00	<i>X</i>
15	SIDE MIRROR GLASS - LH <i>Not</i>	1	\$ 892.00	<i>X</i>
16	REAR DOOR - RH <i>Dented</i>	1	\$ 2,909.00	<i>✓</i>
17	REAR DOOR OUTER SEAL <i>Not</i>	1	\$ 135.00	<i>✓</i>
18	REAR DOOR ATTACHMENT PARTS <i>Not</i>	1	\$ 311.00	<i>X</i>
19	REAR DOOR CATCH	1	\$ 120.00	<i>?</i>
20	REAR DOOR SILL PANEL SEAL <i>Not</i>	1	\$ 135.00	<i>X</i>
SUB TOTAL SPARE PARTS		:	\$ 13,731.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 5810 G

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR DOOR COVER - LH <i>lt</i>	1	\$ 257.00	✓
22	FRONT WHEEL COVER - LH / RH <i>hec</i>	2	\$ 536.00	✓
23	REAR WHEEL COVER - LH <i>lt</i>	1	\$ 268.00	✓
24	REAR DOOR TRIM - LH <i>hec</i>	1	\$ 179.00	x
25	REAR DOOR HANDLE TRIM <i>lt</i>	1	\$ 198.00	✓
26	REAR DOOR HANDLE END CAP TRIM - LH <i>Repair</i>	1	\$ 27.00	x
27	REAR DOOR CORNER TRIM <i>hec</i>	1	\$ 46.00	x
28	FRONT NUMBER PLATE <i>hec</i>	S/N	\$ 60.00	x
29	SUNDRIES <i>?</i>		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 15,552.00	
TOTAL LABOUR CHARGES		:	\$ 8,472.00	
GRAND TOTAL		:	\$ 24,024.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *22/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 07 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT