

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD90Z**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

22 APR 2021

AAD2104-

Not Notified  
 11/10/2020 @ 9900k  
 Runway After Paint

**SHD90Z**

VF1ABL15AUC283229

RENAULT

LATITUDE

20/04/2021

**TOKIO MARINE**

31/08/2016

**PART****LIST**

|                                    |    |            |       |
|------------------------------------|----|------------|-------|
| 1 BUMPER COVER REAR                | \$ | B 561.70   | ✓     |
| 1 BUMPER LOWER REAR                | \$ | B 411.90   | ✓     |
| 1 BUMPER REFLECTOR LH              | \$ | Sm 16.60   | X     |
| 1 BUMPER REFLECTOR RH              | \$ | CAR 16.60  | ✓     |
| 1 BUMPER BRACKET CTR REAR          | \$ | DIT 98.10  | ✓     |
| 1 BUMPER BRACKET SIDE RH REAR      | \$ | DIT 82.10  | ✓     |
| 1 BUMPER RETAINER RH REAR          | \$ | R 59.80    | X     |
| 1 BUMPER BRACKET SIDE LH REAR      | \$ | L 80.80    | X     |
| 1 BUMPER RETAINER LH REAR          | \$ | L 54.20    | X     |
| 1 FENDER PANEL REAR RH             | \$ | B 1,933.20 | ✓     |
| 1 WHEELARCH REAR RH                | \$ | R 275.40   | X     |
| 1 ABSORBER REAR                    | \$ | R 217.30   | X     |
| 1 BUMPER BEAM REAR                 | \$ | B 547.80   | ✓     |
| 1 BUMPER BEAM BRACKET LH REAR      | \$ | R 114.50   | X     |
| 1 BUMPER BEAM BRACKET RH REAR      | \$ | B 114.50   | ✓     |
| 1 OUTER PANEL REAR (End Panel)     | \$ | B 745.80   | ✓     |
| 1 OUTER PANEL REAR (End Panel)TRIM | \$ | R 404.56   | X     |
| 1 BOOT REAR                        | \$ | B 1,677.20 | ✓     |
| 1 BOOT LOCK                        | \$ | R 246.60   | X     |
| 1 BOOT LOCK CATCH                  | \$ | R 41.70    | X     |
| 1 BOOT FINISHER                    | \$ | R 344.70   | X     |
| 1 BOOT WEATHERSTRIP                | \$ | DIT 178.20 | 50/10 |
| 1 BOOT STRUT LH                    | \$ | Sm 145.10  | X     |
| 1 BOOT STRUT RH                    | \$ | Sm 145.10  | X     |
| 1 BOOT HINGE LH                    | \$ | R 254.20   | X     |
| 1 BOOT HINGE RH                    | \$ | R 254.20   | X     |
| 1 BOOT BADGE 'RENAULT'             | \$ | R 82.40    | ✓     |

89-10525

DIT 178.20 50/10

1004-21  
 3088-10

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2104-

**SHD90Z**

|                           |    |          |          |
|---------------------------|----|----------|----------|
| 1 BOOT BADGE              | \$ | 95.80    | ✓        |
| 1 BOOT REFLECTOR LAMP LH  | \$ | 277.70   | X        |
| 1 BOOT REFLECTOR LAMP RH  | \$ | 277.70   | X        |
| 1 SPARE WHEEL PANEL       | \$ | 1,229.40 | X        |
| 1 TAILLAMP LH             | \$ | 401.40   | X        |
| 1 TAILLAMP RH             | \$ | 401.40   | ✓        |
| 1 EXHAUST REAR <i>P1?</i> | \$ | 5,263.60 | ✓ 3260SN |
| 1 EXHAUST CAP REAR        | \$ | 125.40   | ✓        |

|        |           |
|--------|-----------|
| \$     | 17,176.66 |
| 10% \$ | 1,717.67  |
| \$     | 15,458.99 |

**Special Nett**

|                                     |    |        |       |
|-------------------------------------|----|--------|-------|
| 1SET PARKING AID                    | \$ | 700.00 | 400SN |
| 1SET REAR BUMPER CLIP               | \$ | 66.00  | ✓     |
| 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | 10.00  | X     |
| 1SET BUMPER RETAINER RH CLIP RR     | \$ | 20.00  | X     |
| 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ | 10.00  | X     |
| 1SET BUMPER RETAINER CLIP LH RR     | \$ | 20.00  | X     |
| 1SET BUMPER LOWER REAR CLIP         | \$ | 66.00  | ✓     |
| 1 EXHAUST MOUNTING REAR             | \$ | 17.82  | X     |
| 1 LICENSE PLATE WITH HOLDER FRT     | \$ | 120.00 | X     |
| 2 WINDSCREEN SEALANT                | \$ | 150.00 | 40SN  |
| 1 WINDSCREEN MOULDING               | \$ | 200.00 | X     |
| 1 WINDSCREEN INNER SPONGE SEAL      | \$ | 130.00 | 30SN  |

|                |           |
|----------------|-----------|
| TOTAL \$       | 1,509.82  |
| TOTAL PARTS \$ | 16,968.81 |

**LABOUR**

|                                                                                      |    |          |      |
|--------------------------------------------------------------------------------------|----|----------|------|
| To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair. | \$ | 300.00   | 1201 |
| Putty And Spray Painting Of The Affected Portion.                                    | \$ | 3,000.00 | 8801 |

**Trans-cab Auto Services Pte Ltd**

AAD2104-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD90Z**

|                                                                                                                           |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|------|
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 3,000.00 | 1200 |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00   | 90   |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 170.00   | 60   |
| To transfer of bootlid fittings, attachments and perform water seepage test.                                              | \$ | 170.00   | 60   |
| To repair and realign rear exhaust pipe.                                                                                  | \$ | 170.00   | } 80 |
| To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.                                      | \$ | 170.00   |      |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | 170.00   | 100  |
| To transfer of rear windscreen fittings and conduct water seepage test.                                                   | \$ | 170.00   | X    |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00   | X    |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 170.00   | 20   |

**TOTAL \$ 7,880.00****Over All Total \$ 40,307.81****(LUMP SUM)****Repair Days****10 DAYS***8 days***LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary form(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
nature: