

NOT APPROVED

3295.37

71 : 3526.05

Henry Bepain

ROEL

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD 555A -**

Vehicle No.:	<b>SHD555A - ROEL</b>
Chassis No.:	VF1ABL15AUC282637
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	12.02.2017
Third Party Insurer :	MSIG

		<b>PART</b>		<b>LIST</b>	
1	1	BUMPER COVER FRT	\$	B1 968.78	✓ ✓
2	1	BUMPER ABSORBER FRT	\$	303.60	7
3	1	BUMPER BEAM FRT	\$	703.14	7
4	1	BUMPER SPOILER FRT	\$	Sn 139.81	x
5	1	BUMPER FOG LAMP GRILLE RH	\$	Sn 159.40	x
6	1	BUMPER RETAINER FRT LH	\$	Sn 116.47	x
7	1	BUMPER RETAINER FRT RH	\$	DIV 116.47	✓ ✓
8	1	BUMPER SUPPORT FRT RH	\$	Sn 18.37	x
9	1	BUMPER UNDERTRAY FRT	\$	Sn 363.71	x
10	1	RADAITOR GRILLE	\$	Sn 1,313.68	x
11	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	nn 173.32	x
12	1	RADAITOR GRILLE FRAME	\$	Sn 1,041.35	x
13	1	FRAME FULL SUPPORT PANEL	\$	Sn 477.37	x
14	1	LOWER ARM RH	\$	Sn 527.51	x
15	1	KUNCKLE ARM RH	\$	Sn 651.53	x
16	1	ABSORBER FRT RH	\$	Sn 277.34	x
17	1	ABSORBER DUST COVER	\$	Sn 175.93	x
18	1	BONNET	\$	R 1,493.56	x
19	1	WIPER RESERVOIR	\$	Sn 173.60	x
20	1	WIPER RESERVOIR MOTOR	\$	Sn 91.78	x
21	1	HEADLALMP RH	\$	MSIG 911.10	✓ ✓
22	1	FENDER PANEL FRT RH	\$	B1 602.95	✓ ✓
23	1	FENDER WHEELARCH FRT RH	\$	Sn 107.33	x
24	1	DOOR PANEL FRT RH	\$	R 2,188.20	x
25	1	DOOR SEAL FRT RH	\$	Sn 55.30	x
26	1	DOOR MIRROR RH	\$	Sn 1,141.08	x

<b>TOTAL</b>	\$	<b>14,292.67</b>
<b>10%</b>	\$	<b>1,429.27</b>
	\$	<b>12,863.40</b> 2339.37

# TRANS-CAB AUTO SERVICES PTE LTD

ROEL

NO.2, ANG MO KIO ST63 SINGAPORE 569111  
 TEL NO. 6287 6666 FAX NO. 6257 1330  
 CO/GST REG NO. 201019626G

SHD 555A -

## Special Nett

1	1SET	FRONT BUMPER CLIP	\$	na	66.00	✓
2	1SET	WHEELARCH CLIP RH	\$	na	66.00	X
3	1	DOOR STICKER "Trans-cab"	\$	na	80.00	X
4	1	DOOR STICKER "Classic"	\$	na	30.00	X
5	1	CAP HUB RH FRT	\$	na	35.00	X
6	1	RIM RH FRT	\$	na	385.00	X
7	1	TYRE RH FRT	\$	na	330.00	X

<b>TOTAL</b>	<b>\$</b>	<b>992.00</b>	<i>66.00</i>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>13,855.40</b>	

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>4000</i> ✓
To Check Electrical Lighting Concerned.	\$	170.00	<i>200</i> ✓
Putty and spray painting of the affected	\$	2,800.00	<i>4400</i> ✓
To check brake efficiency, final checking and testing.	\$	na	380.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
Towing Fees	\$	na	120.00 X
To transfer of tire, rim and on wheel	\$	na	170.00 X
To rust-proofing of the affected areas.	\$	170.00	<i>300</i> ✓
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na	170.00 X

<b>TOTAL</b>	<b>\$</b>	<b>7,580.00</b>	<i>890.00</i>
<b>Over All Total</b>	<b>\$</b>	<b>21,435.40</b>	

(PARTS BY PARTS) Repair Days *10 Days*  
*2 days*