

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. CHONG JEAH YOKE

BLK 218 PASIR RIS STREET 71 #10-156
S 510218

Attention : Motor Claim Department

Contact : 92347770

Estimate : ES001438

Date : 21/04/2021

Vehicle Num. : SJQ 7029P

Make/Model : TOYOTA VIOS 1.5 E A

Chassis/Eng# :

Accident Date : 19/04/2021

Claim No. :

Reference :

Policy No. :

TP Chim

Ju>

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 PC	LIST ITEMS :		
2.	1 PC	REAR BUMPER <i>deformed</i>		496.00 ✓
3.	1 PC	REAR LAMP <i>new</i>		310.00 +
4.	1 PC	REAR END PANEL <i>deformed</i>		645.00 ✓
5.	1 PC	REAR LAMP PANEL <i>new</i>		135.00 +
6.	1 PC	REAR BUMPER LOWER LIP <i>deformed</i>		350.00 ✓
7.	1 PC	REAR BOOT <i>new</i>		667.00 +
8.	1 PC	REAR BOOT LOCK <i>new</i>		100.00 +
8.	1 PC	REAR BOOT LOCK CABLE <i>new</i>		80.00 +
List Total S\$:				2,783.00
LABOUR :				
KNOCKING, CUTTING, JACKING WELDING ETC				800.00 <i>500</i>
SPRAY PAINTING				800.00 <i>400</i>
TO CHECK WIRING AND SYSTEM FUNCTION				80.00 <i>30</i>
Labour Total S\$:				1,680.00

1491

1118.25

930

Total S\$: 4,463.00

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 2048.25

L/S: 1.6k.

04 Days