



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Submit to insurance.

Car Number: SMV6024Y

Model : Mercedes GLB200

Damaged Area: (Rear Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorized
LKR
26/4/21
2/s \$8200 6 days.
Shanghai After repn.

Parts / Material :

1	Rear bumper top	De/turn 129/84	\$ 1,486.00	—
2	Rear bumper centre	be 612.57	\$ 986.00	—
3	Rear bumper centre chrome garnish top	SVC	\$ 395.00	X
4	Rear bumper lower	ground/turn 425.21	\$ 755.00	—
5	Rear bumper lower chrome garnish	CNA 659.69	\$ 1,125.00	✓
6	Rear bumper exhaust support bracket @ SGD 78.00	11	\$ 156.00	X
7	Rear bumper reflector @ SGD 165.00	11	\$ 330.00	X
8	Rear bumper sensor @ SGD 295.00	SVC	\$ 1,180.00	X
9	Rear bumper sensor holder @ SGD 65.00	11	\$ 260.00	X
10	Rear bumper sensor wireharness	11	\$ 520.00	X
11	Rear bumper bracket corner @ SGD 85.00	CNA 62x2=124	\$ 170.00	—
12	Rear bumper side bracket @ SGD 140.00	11	\$ 280.00	X
13	Rear bumper centre frame bracket	CNA 281.21	\$ 390.00	—
14	Rear bumper reinforcement	3mt 500.55	\$ 1,425.00	—
15	Rear bumper clips (Set)	11 500.00	\$ 60.00	—
16	Taillamp @ SGD 1115.00	11	\$ 2,230.00	X
17	Taillamp panel @ SGD 740.00	11	\$ 1,480.00	X
18	Tailgate panel	DS 3025.29	\$ 3,760.00	—
19	Tailgate number plate lamp garnish	11	\$ 680.00	X
20	Tailgate lamp @ SGD 720.00	11	\$ 1,440.00	X
21	Tailgate logo	11 135	\$ 155.00	—
22	Tailgate emblem GLB 200	11 122	\$ 138.00	—
23	Tailgate emblem AMG	11 152	\$ 175.00	—
24	Tailgate Stopper @ SGD 25.00	11	\$ 50.00	X
25	Tailgate inner trim	11	\$ 720.00	X
26	Tailgate top lock	shold 294.98	\$ 590.00	—
27	Tailgate lower lock	11	\$ 95.00	X
28	Tailgate weather strip	11	\$ 510.00	X
29	Tailgate moulding w/glass	11	\$ 2,890.00	X
30	Tailgate feet sensor	11	\$ 586.00	X
31	Rear end panel	606.90 1947.60	\$ 1,480.00	—
32	Rear end panel inner garnish	SVC	\$ 645.00	X
33	Rear floor panel	11	\$ 2,640.00	X
34	Rear floor panel top board	11	\$ 1,340.00	X
35	Rear fender arc garnish @ SGD 375.00	11	\$ 750.00	X
36	Rear fender arc garnish clips	11	\$ 60.00	X
37	Rear exhaust box	11	\$ 3,860.00	X
38	Rear exhaust chrome pipe @ SGD 470.00	11	\$ 940.00	X
39	Rear exhaust insulator @ SGD 580.00	11	\$ 1,160.00	X
40	Rear exhaust mounting @ SGD 70.00	11	\$ 280.00	X

Parts : \$ 38,172.00

Less Parts 10% : \$ 3,817.20

Total Parts : \$ 34,354.80

Special Net Items :

Rear End Panel Sealant	\$	80.00	50
Rear Floor Panel Sealant	\$	80.00	X
Rear Tailgate Glass Sealant	\$	80.00	40
Rear Number Plate W/Garnish	\$	68.00	X

Total S/N Parts : \$ 308.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,400.00	800
To Putty, Spray Paint on Affected Accident Areas	\$	1,400.00	800
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Remove & Install Rear Tailgate Components Trim & Garnish	\$	150.00	60
To Remove & Install Rear Spare Tyre Components, Trim & Garnish	\$	150.00	80
To Remove & Install Rear Tailgate Glass	\$	150.00	120
To Re-Position, Drill & Install Reverse Sensor	\$	150.00	50
To Conduct Water Leakage Test	\$	150.00	X
To Rust Proof Affected Areas	\$	200.00	60

Total Labour : \$ 3,800.00

TOTAL PARTS :	\$	34,354.80
TOTAL SPECIAL NET ITEM	\$	308.00
TOTAL LABOUR :	\$	3,800.00
TOTAL REPAIR COST :	\$	38,462.80

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 915431
1/2
P23887