



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCV9001L

Finalization

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Repair

Vehicle & Document Information

WIP No 49673
Reg No/Reg Date SCV9001L / 22/05/2017
Date In/Mileage 27/04/2021 / 51661
Chassis No WDD2050402R242402
Engine No 27491030760091
Make/Model MB/MB C 180 SEDAN (W205) "AMG LINE"
Colour/Trim 021 197 Obsidian B1/ 041 141 Black ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	27/05/2021/ 23:02	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services								
M BPNSUN POLICY NO/ACC DATE : 1700006532 // 22-04-2021 DRIVE IN: 22-04-2021 // TP CAR NO: SHB176X (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: 27-04-2021 // LKK RASUL BY/AUTHORIZED ON : ANA // 23-04-2021								
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT							0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT								120.00
S BPNSUB LABOUR TO REMOVE AND INSTALL 1PC TYRE FROM RIM								60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								540.00
A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH								1440.00
A BPIRES RESPRAY FRONT BUMPER & FRONT LEFT FENDER								1200.00
X LH/F HEADLAMP					1.00	3349.33	00.00	3349.33
X LH/F DISC WHEEL					1.00	1449.01	00.00	1449.01
X FRT BUMPER					1.00	1832.25	00.00	1832.25
X LH/F BUMPER BRACKET					1.00	12.88	00.00	12.88
X LH/F BASIC MOUNTING FOR BUMPER					1.00	84.94	00.00	84.94
X LH/F OUTER PARKING SENSOR					1.00	182.48	00.00	182.48
X LH/F PARKING SENSOR SEAL					1.00	6.35	00.00	6.35
X LH/F BOTTOM GARNISH					1.00	170.67	00.00	170.67
X LH/F BOTTOM GRILLE					1.00	73.67	00.00	73.67
X LH/F FENDER					1.00	948.95	00.00	948.95
X LH/F BOTTOM GRILLE HOLDER					1.00	69.42	00.00	69.42
X LH/F CROSS MEMBER BRACKET					1.00	77.53	00.00	77.53

Alan Quek

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 67714377 HP: 91865112 Fax: 68721272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 11,997.48
7% GST on 11997.48 839.82
Total Payable 12,837.30

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCV9001L

SUPPLEMENTARY

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 49673
Reg No/Reg Date SCV9001L / 22/05/2017
Date In/Mileage 27/04/2021 / 51661
Chassis No WDD2050402R242402
Engine No 27491030760091
Make/Model MB/MB C 180 SEDAN (W205) "AMG LINE"
Colour/Trim 021 197 Obsidian Bl/ 041 141 Black ARTIC

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WF001862	Credit	27/05/2021/ 23:02	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 1700006532 // 22-04-2021
DRIVE IN: 22-04-2021 // TP CAR NO: SHB176X (FIRST CAPITAL INSURANCE)
DATE IN/DATE SURVEY: 27-04-2021 // LKK RASUL
BY/AUTHORIZED ON : ANA // 23-04-2021

X LH/F BOTTOM GRILLE HOLDER
X LH/F CROSS MEMBER BRACKET

1.00	69.42	00.00	69.42
1.00	77.53	00.00	77.53

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	146.95
7% GST on	146.95	10.29
Total Payable		157.24

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany