



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCV9001L

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No **49673**
Reg No/Reg Date **SCV9001L / 22/05/2017**
Date In/Mileage **1 / 0**
Chassis No **WDD2050402R242402**
Engine No **27491030760091**
Make/Model **MB/MB C 180 SEDAN (W205) "AMG LINE"**
Colour/Trim **021 197 Obsidian Bl/ 041 141 Black ARTIC**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WF001862	Credit	22/04/2021/ 17:50	AQ	305 / Alan Quek Ai Lun					
<p>M BPNSUN POLICY NO/ACC DATE : 1700006532 // 22-04-2021 DRIVE IN: 22-04-2021 // TP CAR NO: SHB176X (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p> <p>A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT</p> <p>A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT</p> <p>S BPNSUB SUPPLY & TRANSFER 1PC FRONT LEFT RIM PURCHASE ORDER NO:</p> <p>A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT</p> <p>A BPILAB REMOVE & REPLACE FRONT BUMPER, FRONT LEFT FENDER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.</p> <p>A BPIRES RESPRAY FRONT BUMPER & FRONT LEFT FENDER</p> <p>M LH/F HEADLAMP</p> <p>M LH/F HEADLAMP CONTROL UNIT</p> <p>M LH/F DISC WHEEL</p> <p>M FRT BUMPER</p> <p>M LH/F BUMPER BRACKET</p> <p>M LH/F BASIC MOUNTING FOR BUMPER</p> <p>M LH/F OUTER PARKING SENSOR</p> <p>M LH/F PARKING SENSOR SEAL</p> <p>M LH/F BOTTOM GARNISH</p> <p>M LH/F BOTTOM GRILLE</p> <p>M LH/F FENDER</p> <p>M LH/F WHEEL ARCH COVER</p>									
								0.10	380.00
									120.00
									60.00
									540.00
									2400.00
									1500.00
						1.00	3349.33	00.00	3349.33
						1.00	629.47	00.00	629.47
						1.00	1449.01	00.00	1449.01
						1.00	1832.25	00.00	1832.25
						1.00	12.88	00.00	12.88
						1.00	84.94	00.00	84.94
						1.00	182.48	00.00	182.48
						1.00	6.35	00.00	6.35
						1.00	170.67	00.00	170.67
						1.00	73.67	00.00	73.67
						1.00	948.95	00.00	948.95
						1.00	130.18	00.00	130.18

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett **13,870.18**
7% GST on **13870.18** **970.91**

Total Payable **14,841.09**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany