



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFN 7828M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,754.75	1,415.20
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	86.34	-
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	86.34	-
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	86.34	-
1	FRONT BUMPER PROTECTOR (CONSISTENT)	DENTED	62.58	62.58
1	FRONT BUMPER PROTECTOR MOULDING (CONSISTENT)	DENTED	120.68	120.68
1	LH FOG LAMP (CONSISTENT)	SERVICEABLE	342.58	-
1	LH FONG LAMP COVER (CONSISTENT)	SERVICEABLE	33.95	-
1	LH FOG LAMP CHROME (CONSISTENT)	SERVICEABLE	121.31	-
1	FRONT LH FENDER (CONSISTENT)	BENT	883.08	883.08
1	FRONT LH LOWER ARM (CONSISTENT)	SERVICEABLE	895.96	-
1	FRONT LH KNUCKLE ARM (CONSISTENT)	BENT	569.45	569.45
1	FRONT LH SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	787.25	-
1	LH HEAD LAMP (CONSISTENT)	SERVICEABLE	2,872.69	-
1	RH SIDE MIRROR SIGNAL LAMP (CONSISTENT)	SCRATCHED	135.27	135.27
	LESS 10% DISCOUNT		-	-318.63
			8,838.57	2,867.63
<b>SPECIAL NETT ITEMS</b>				
1	SPORT RIM (SN)(CONSISTENT)	DENTED	500.00	500.00
			500.00	500.00
<b>LABOUR</b>				
	REMOVE & FIX BACK FRONT BUMPER ,FENDER ,HEAD LAMP ,REPAIR ,WHEEL HOUSING .		700.00	450.00
	REMOVE & FIX BACK LH UNDERCARRIAGE.		250.00	80.00
	COMPUTERSE WHEEL ALIGNMENT.		140.00	60.00
	REMOVE & FIX BACK LH SIDE MIRROR SIGNAL .		80.00	20.00
	SPRAY PAINTING.		900.00	440.00
			2,070.00	1,050.00
<b>GRAND TOTAL</b>			<b>11,408.57</b>	<b>4,417.63</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,500.00</b>
---	--	--	-----------------

Report Ref No. CC4/ASM21005093/Kpa3q2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**