

# GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A  
 #02-03 AMK AUTOPOINT 568047  
 Tel No. : 64837111 Fax No. : 64837221  
 E-Mail : guanhinmotor@yahoo.com  
 Buss. Reg. No. : 06035200X

*NOT Authorized*  
*L1 Rmp @ 3500/h*  
*Resurvey After Paint*  
*5 days*

AXA INSURANCE PTE LTD  
 8 SHENTON WAY  
 #24-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department  
 Contact : 63387288

Estimate : ES000938

Date : 26/04/2021  
 Vehicle Num. : SFN 7828 M  
 Make/Model : MERCEDES BENZ E200K-2008  
 Chassis/Eng# : WDB2110412B392839/27195631129177  
 Accident Date : 19/04/2021  
 Claim No. :  
 Reference :  
 Policy No. : (11/03/2009)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		LIST ITEMS :		
1.	1	FRONT BUMPER <i>1415.20</i>	<i>Bu</i> 1,754.75	<i>✓</i>
2.	1	FRONT BUMPER SPONGE	<i>Sm</i> 86.34	<i>X</i>
3.	1	FRONT BUMPER SPONGE	<i>Sm</i> 86.34	<i>X</i>
4.	1	FRONT BUMPER SPONGE	<i>Sm Net</i> 86.34	<i>X</i>
5.	1	FRONT BUMPER PROTECTOR	<i>Net</i> 62.58	<i>✓</i>
6.	1	FRONT BUMPER PROTECTOR MOULDING	<i>Net</i> 120.68	<i>✓</i>
7.	1	LH FOG LAMP	<i>Sm</i> 342.58	<i>X</i>
8.	1	LH FONG LAMP COVER	<i>Sm</i> 33.95	<i>X</i>
9.	1	LH FOG LAMP CHROME	<i>Sm</i> 121.31	<i>X</i>
10.	1	FRONT LH FENDER	<i>Ry</i> 883.08	<i>✓</i>
11.	1	FRONT LH LOWER ARM	<i>Sm</i> 895.96	<i>X</i>
12.	1	FRONT LH KNUCKLE ARM	<i>BT</i> 569.45	<i>✓</i>
13.	1	FRONT LH SHOCK ABSORBER	<i>Sm</i> 787.25	<i>X</i>
14.	1	LH HEAD LAMP	<i>Sm</i> 2,872.69	<i>X</i>
15.	1	RH SIDE MIRROR SIGNAL LAMP	<i>Sm</i> 135.27	<i>✓</i>
		List Total S\$ :	<i>105</i> 8,838.57	
		SPECIAL NETT ITEMS :		
1.	1	SPORT RIM	<i>Net</i> 500.00	<i>✓</i>
		Special Nett Total S\$ :	500.00	
		LABOUR :		
		REMOVE & FIX BACK FRONT BUMPER,FENDER, HEAD LAMP,REPAIR,WHEEL HOUSING	700.00	<i>450</i>
		REMOVE & FIX BACK LH UNDERCARRIAGE	250.00	<i>80</i>
		COMPUTERSE WHEEL ALIGMENT	140.00	<i>60</i>

CONTINUE / ...

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**GUAN HIN MOTOR WORKSHOP**

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

AXA INSURANCE PTE LTD

8 SHENTON WAY

#24-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288

**Estimate : ES000938**

Date : 26/04/2021

Vehicle Num. : SFN 7828 M

Make/Model : MERCEDES BENZ E200K-2008

Chassis/Eng# : WDB2110412B392839/27195631129177

Accident Date : 19/04/2021

Claim No. :

Reference :

Policy No. : (11/03/2009)

S/N	Quantity	Particular	Unit Price	Amount S\$
		REMOVE & FIX BACK LH SIDE MIRROR SIGNAL SPRAY PAINTING		80.00 900.00
		Labour Total S\$ :		2,070.00

201  
4401

E. &amp; O.E.

Total S\$ : 11,408.57

=====

for GUAN HIN MOTOR WORKSHOP