



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20210422/0320		LOCATION OF FIRE: Along Serangoon Road towards Kitchener Link (near lamp post no. 71) Singapore	
FIRE REPORTED ON : 22 April 2021			
TIME OF CALL : 10:24:02 hrs			
STATION COVERAGE : Central Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine compartment of a Hyundai i40 car (SHD3272X) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using a compressed air foam backpack and a hose reel jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Electrical origin at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine compartment, windscreen, bonnet and headlights were damaged. The dashboard and interior of the car sustained varying degrees of heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY: EE YONG EN JOEL for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.