



Service Requests

Messages

Claims



Service Request Details

Claim	S1M038QS
Reference	CS4/ASM21005094/Ntce2
Loss Date	22 April 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Report Date	23 Apr 2021 4:33:28 PM
Request Date	27 April 2021
Due Date	
Services	Own Damage Investigation

Actions

Next Step Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident	SHD3272X
Vehicle	
Registration #	
Make	HYUNDAI I40 (EURO 5)
Model	HYUXXX

Service Address

383 SIN MING DRIVE, , , 575717

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions
1) FIRE
Case

Messages2InvoicesHistoryDocumentsAssessmentMetricsNotes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM_LKKInvoice_AC2103661.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	25 May 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 Total Loss Report_SHD 3272X.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	25 May 2021
 Fire Report_SHD 3272X.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	25 May 2021
 PRR_Pdf_Along Serangoon Rd (SHD3272X)(1).pdf.pdf	Other	Other	LKK AUTO CONSULTANTS PTE LTD (OD)	25 May 2021
 SHD 3272X FIRE INVESTIGATION REPORT.pdf.pdf	Reports & Statement	Investigator / Adjustor Report	LKK AUTO CONSULTANTS PTE LTD (OD)	12 May 2021
 LTA.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	29 April 2021
 PRELI ADVISED SHD 3272X - 1.pdf.pdf	Other	Other	LKK AUTO CONSULTANTS PTE LTD (OD)	29 April 2021
 Survey photo.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	27 April 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRELI ADVISED SHD 3272X.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	27 April 2021