

- Home
- Service Requests
- Messages
- Claims

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

| | |
|------------------|--|
| Involving | TPVD UNKNOWN UNKNOWN (GBE6492Z) |
| Date of Loss | 23 April 2021 |
| Time of Loss | 8:00 |
| Loss Description | SH9677X (INSD) HIT REAR OF GBE6492Z (TP) |
| Comment | <input type="text"/> |

Workshop Details

| | |
|---------------------------|-----------------------------------|
| Total Rebate Amount | <input type="text" value="0"/> |
| Nett Loss Amount | \$0.00 |
| Assigned Workshop | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Days of work completion * | <input type="text" value="20"/> |

-  Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
 - Vehicle & Driver Details**
 - Vehicle Condition
 - Taxes & Ratio
 - Parts & Labour
 - Miscellaneous
- Summary

Vehicle & Driver Details

| | | | |
|-----------------------|--|---------------------|---|
| Vehicle Registration# | GBE6492Z | Purchase Date | <input type="text" value="DD/MM/YYYY"/>  |
| Registration State | <input type="text" value="SINGAPORE"/> | Registration Date * | <input type="text" value="18/02/2016"/>  |
| Mileage | <input type="text" value="181606"/> | Age of Vehicle | 5 |

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|--------------------|--------------------|-----------------------------------|
| Manufacturing Year | | <input type="text" value="2015"/> |

Driver Details

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|-------------|------------------|-------------------------|
| Driver Name | TBC | <input type="text"/> |

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|-----------------|--------------------|-------------------------------|
| Make | TPVD UNKNOWN | NISSAN |
| Model | UNKNOWN | NV350 PANEL VAN 2.5 ! |
| Type | | <input type="text" value=""/> |
| Type of Paint | | <input type="text" value=""/> |
| Chassis No | | JN1MC2E26Z0005740 |
| Engine No | | YD25387329A |
| Engine Capacity | | 2488 |
| Sum Insured | | 0 |

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|-------------------------|------------------|--|
| Date of Birth | | DD/MM/YYYY  |
| Age | 0 | |
| Occupation | Unknown | <input type="text" value=""/> |
| Education Qualification | Other | <input type="text" value=""/> |
| Driving Experience | 0 | |
| Driver License # | | <input type="text" value=""/> |
| License Type | | <input type="text" value=""/> |
| License Issue Date | | DD/MM/YYYY  |

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|--------------|--------------------|------------------------|
| Market Value | | 0 |

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|-------------------------|-------------------------|--|
| License Expiration Date | | DD/MM/YYYY  |
| Address | SG, Singapore | |
| Address type | Personal Correspondence | <input type="text" value="v"/> |
| Gender | Unknown | <input type="text" value="v"/> |
| Marital status | Unknown | <input type="text" value="v"/> |
| Identification # | TBC | |

◀ Assessment Details

- General & Workshop Details
 - Vehicle & Driver Details
 - Vehicle Condition**
 - Taxes & Ratio
 - Parts & Labour
 - Miscellaneous
- Summary

Detailed Assessment

| | |
|---|---|
| Inspection Date * | <input type="text" value="26/04/2021"/>  |
| Total Loss | <input type="button" value="Yes"/> <input type="button" value="No"/> |
| Towing Charges | <input type="text" value="0"/> |
| Voluntary Excess | <input type="text" value="0"/> |
| Compulsory Excess | <input type="text" value="0"/> |
| Young/Inexperienced/ Unnamed Driver Excess | <input type="text" value="0"/> |

Condition of Vehicle at time of survey

| | |
|----------------------------|--|
| General condition | <input type="text" value="Good"/> ▾ |
| Steering (Serviceable) | <input type="button" value="Yes"/> <input type="button" value="No"/> |
| Footbrake (Serviceable) | <input type="button" value="Yes"/> <input type="button" value="No"/> |
| Handbrake (Serviceable) | <input type="button" value="Yes"/> <input type="button" value="No"/> |
| Engine Modification | <input type="button" value="Yes"/> <input type="button" value="No"/> |
| Pre-accident condition | <input type="text" value="Good"/> ▾ |

Other Excess

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

-  Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio**
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

| | | | |
|-------------|---------------------------------|-------------|----------------------------------|
| Depr./Bttr% | <input type="text" value="0"/> | Salvage% | <input type="text" value="0"/> |
| Discount% | <input type="text" value="10"/> | Settlement% | <input type="text" value="100"/> |

Paint Labour/Material Ratio

| | | | | | |
|----------------------|---------------------------------|-----------|----------------------------------|--|---|
| Paint Labour Ratio | <input type="text" value="20"/> | Cash Loss | <input type="text" value="Yes"/> | <input checked="" type="text" value="No"/> | Part a r t S u p p l i e d b y |
| Paint Material Ratio | <input type="text" value="80"/> | | | | |

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio **Parts & Labour** Miscellaneous Summary

Parts

| <div style="display: flex; justify-content: space-around; border: 1px solid green; padding: 2px;"> Add Approve Deny Submit All </div> | | | | | | | | | | | | | |
|---|-------|-----------|----------|------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|
| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT |
| | 0 | 1 | | TAILGATE | Dented | 0 | 1816.7 | No | 0 | 10 | 0 | 0 | 1635.03 |
| | 0 | 1 | | TAILGATE GLASS | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 1 | | TAILGATE VIEW MIRROR | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 1 | | TAILGATE WIPER ARM | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 1 | | TAILGATE WIPER MOTOR | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 1 | | TAILGATE EMBLEM NISSAN | Necessary | 0 | 60 | No | 0 | 10 | 0 | 0 | 54 |
| | 0 | 1 | | TAILGATE EMBLEM NV350 | Necessary | 0 | 60 | No | 0 | 10 | 0 | 0 | 54 |

VendorEngage

| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT |
|---|-------|-----------|----------|--------------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|
|  | 0 | 1 | | TAILGATE OUTER CHROME MOULDING | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILGATE LICENCE LAMP | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE INNER LOCK | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE INNER TRIMS | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE INNER TRIMS CLIP | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE INNER LOCK ACTUATOR | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE LOCK STRIKER | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILGATE DAMPERS L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILGATE HINGE L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILGATE SIDE STOPPERS L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |

VendorEngage

| EDIT | SR NO | QUANTITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT |
|---|-------|----------|----------|------------------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|
|  | 0 | 2 | | TAILGATE SIDE STOPPER STICKERS L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | TAILGATE THIRD BRAKE LIGHT | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILLAMP L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILLAMP FILLER PANNEL INNER L-R | Repair | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | TAILLAMP FILLER PANNER OUTER L-R | Repair | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR BUMPER | Deformed | 0 | 667.2 | No | 0 | 10 | 0 | 0 | 600.48 |
|  | 0 | 1 | | REAR BUMPER CLIPS | Necessary | 0 | 27 | No | 0 | 10 | 0 | 0 | 24.3 |
|  | 0 | 4 | | REAR BUMPER SIDE HOLDERS L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR END PANEL INNER | Repair | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR END PANEL OUTER | Dented | 0 | 147.1 | No | 0 | 10 | 0 | 0 | 132.39 |
|  | 0 | 1 | | REAR END PANEL TOP MOUNTING | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |

VendorEngage

| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT |
|---|-------|-----------|----------|--|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|
|  | 0 | 1 | | REAR EXHAUST SILENCER | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 3 | | REAR EXHAUST MOUNTING | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR FLOOR MAT | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR FLOOR COMPARTMENT PANEL | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | REAR STEP PANEL | Bent | 0 | 152.1 | No | 0 | 10 | 0 | 0 | 136.89 |
|  | 0 | 1 | | REAR FLOOR PANEL LOWER MEMBER - CTR | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | REAR FENDER L-R | Repair | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | REAR FENDER OUTER COVER L-R | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 2 | | REAR FENDER INNER TRIM BOARD | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
|  | 0 | 1 | | SET REAR FENDER INNER TRIM BOARD CLIPS | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |

VendorEngage

| EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT |
|------|-------|-----------|----------|--|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|
| | 0 | 2 | | REAR FENDER INNER LOWER SIDE COVERS | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 2 | | REAR FENDER INNER PANELS | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 2 | | REAR FENDER WHEEL HOUSING | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |
| | 0 | 2 | | REAR FENDER INNER FRAME MEMBER L-R - TOP | Serviceable | 0 | 0 | No | 0 | 0 | 0 | 0 | 0 |

Labour

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | REMOVE |
|------|-------|-------------------------|--|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|--------|
| | 0 | | TOWING | 0 | 0 | 0 | 0 | Deny | | |
| | 0 | | TO REMOVE REFIX TAILGATE GLASS | 0 | 100 | 0 | 0 | Reviewing | | |
| | 0 | | TO CHECK ELECTRICAL WIRING | 0 | 30 | 0 | 0 | Reviewing | | |
| | 0 | | TO REMOVE REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR | 0 | 0 | 0 | 0 | Deny | | |
| | 0 | | TO REMOVE REFIX ENDING MOUNTING | 0 | 0 | 0 | 0 | Deny | | |

VendorEngage

| EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT | REMOVE |
|---|-------|-------------------------|---|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|---|
|  | 0 | | TO RESPRAY UNDER COATING | 0 | 60 | 0 | 0 | Reviewing | |  |
|  | 0 | | TO RESPRAY ACCIDENT PARTS | 0 | 800 | 0 | 0 | Reviewing | |  |
|  | 0 | | PANEL BEATING CUT WELD REMOVE AND REPLACING ABOVE PARTS | 0 | 880 | 0 | 0 | Reviewing | |  |

Home Service Requests Messages Claims

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour **Miscellaneous**

Summary

| Add | | Approve | | Deny | | Submit All | |
|------|-------|------------------------------|-----------|------------------|-----------------|------------|--------|
| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
| | 0 | DAYS OF REPAIR : 4 DAYS | Reviewing | 0 | 0 | | |
| | 0 | 1 TUBE TAILGATE GLASS SELANT | Reviewing | 0 | 40 | NECESSARY | |

| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|---|-------|---------------------------|-----------|------------------|-----------------|---------------|---|
|  | 0 | REAR STICKER 70KM | Reviewing | 0 | 10 | NECESSARY |  |
|  | 0 | REAR STICKER 6 PAX | Reviewing | 0 | 10 | NECESSARY |  |
|  | 0 | REAR NUMBER PLATE | Deny | 0 | 0 | NOT NECESSARY |  |
|  | 0 | 1 SET REAR REVERSE SENSOR | Reviewing | 0 | 200 | SHORTED |  |

- Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$4,767.09

| CATEGORY | ESTIMATE | ADJUSTED |
|---------------|----------|----------|
| Spare Parts | | |
| Labour | | |
| Spare Parts | | |
| Miscellaneous | | |

Submit for Review

-  Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous**

Summary

| Add | | Approve | | Deny | | Submit All | |
|--|-------|----------------|-----------|------------------|-----------------|------------|--|
| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|  | 0 | FINAL LUMP SUM | Reviewing | 0 | 3800 | |  |

- Home
- Service Requests
- Messages
- Claims

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Estimated Claim Amount \$0.00 Adjusted Claim Amount \$3,800.00

| CATEGORY | ESTIMATE | ADJUSTED |
|----------|----------|----------|
|----------|----------|----------|

Miscellaneous

Submit for Review