

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0350/2021/HR
DATE : 22-Apr-21
WIP : 24194

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. VISHAL AGARWAL
ADDRESS : 78 BAYSHORE ROAD
#22-21
SINGAPORE 469991
TELEPHONE : HP +65 82016384
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMK 9638 P**
MODEL CODE : Q5 SPORT 2.0 TFSI qu
MODEL YEAR : 30/4/2019
ENGINE NO : DAX 052277
CHASSIS NO : WAUZZZF5Y5K2044398
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Apr-21
PLACE OF ACCIDENT : NEAR 279 BALESTIER RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 9638 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00 1000 ✓	✓
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS. //	\$ 4,000.00 1500 ✓ 550 x 2 = 1100 A/c Trim x 2 = 400	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ 7,872.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Re-hon d</i>	1	\$ 1,567.00	✓ 1089.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 293.00	+
3	FRONT BUMPER SECURING STRIP - LH <i>Not nec.</i>	1	\$ 38.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH <i>cracked.</i>	1	\$ 113.00	✓ 90
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 144.00	+
6	FRONT BUMPER SPOILER <i>new</i>	1	\$ 763.00	x
7	FRONT BUMPER UNDERRUN BAR <i>new</i>	1	\$ 518.00	+
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 173.00	x
9	FRONT RADIATOR GRILLE <i>cracked.</i>	1	\$ 3,530.00	✓ 2824
10	"QUATTRO" EMBLEM <i>new</i>	1	\$ 106.00	✓ 84.80
11	FRONT RADIATOR STRIKER PLATE <i>cracked.</i>	1	\$ 244.00	✓ 194.80
12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cracked</i>	1	\$ 581.00	✓ 464.40
13	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH <i>cracked</i>	1	\$ 92.00	✓ 73.20
14	FRONT BUMPER LOCKING CLIP <i>new</i>	2	\$ 8.00	+
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked.</i>	1	\$ 177.00	✓ 141.60
16	FRONT BUMPER CARRIER <i>new</i>	1	\$ 981.00	+
17	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 129.00	✓ 102.80
18	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	+
19	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	✓ 10.88
20	AIR CONDITIONER STICKER <i>new</i>	1	\$ 20.00	✓ 15.52
SUB TOTAL SPARE PARTS		:	\$ 9,510.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

S/N	PARTS DESCRIPTION	QTY		DAMAGED PAI	
				S/NETT	
21	FRONT HORN LOW TONE - LH	1	\$	195.00	+
22	FRONT INNER PARKING AID SENSOR	1	\$	244.00	+
23	FRONT OUTER PARKING AID SENSOR	1	\$	244.00	+
24	FRONT PARKING AID SENSOR SEAL RING	4	\$	14.00	+
25	FRONT BONNET <i>Dented</i>	1	\$	4,058.00	✓ <i>3246.40</i>
26	FRONT BONNET LID HINGE - LH / RH	1	\$	322.00	+
27	FRONT BONNET ATTACHMENT PARTS	1	\$	141.00	+
28	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$	84.00	✓ <i>65.68</i>
29	FRONT BONNET STRIKER	1	\$	240.00	+
30	FRONT BONNET LOCK	2	\$	427.00	+
31	FRONT BONNET BOWDEN CABLE - CENTER	1	\$	58.00	+
32	FRONT BONNET RELEASE ELEMENT	1	\$	58.00	✓ <i>46</i>
33	FRONT BONNET RELEASE LEVER	1	\$	14.00	+
34	HEADLIGHT MOUNTING - LH / RH	2	\$	236.00	?
35	HEADLIGHT - LH / RH	2	\$	16,382.00	✓ <i>8192 6552.80</i>
36	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	280.00	+
37	HEADLIGHT HOSE	1	\$	125.00	+
38	FRONT WHEEL SPOILER - LH	1	\$	160.00	+
39	FRONT WHEEL ARCH COVER - LH / RH	2	\$	1,264.00	✓ <i>1011.20</i>
40	FRONT RADIATOR AIR GUIDE - LH	1	\$	58.00	✓ <i>46.32</i>
TOTAL SPARE PARTS		:	\$	24,546.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT RADIATOR AIR GUIDE - UPPER / LOWER <i>2x</i>	2	\$ 96.00	+
42	FRONT RADIATOR AIR GUIDE - CENTER <i>1x</i>	1	\$ 42.00	+
3	FRONT NUMBER PLATE <i>Nec</i>	S/N	\$ 60.00	✓ <i>60</i>
44	SUNDRIES <i>Rec.</i>		\$ 250.00	? <i>22-24</i>
TOTAL SPARE PARTS		:	\$ 34,504.00	
TOTAL LABOUR CHARGES		:	\$ 7,872.00	
GRAND TOTAL		:	\$ 42,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

[Faint signature box with lines for signature and date]

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0350/2021/HR

14-May-21

CHANG

1 of 1

SMK 9638 P

Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓ ✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,800.00	1250 1500
3	TO REPAIR LHS FRONT FENDER.	\$ 800.00	550 X.
4	TO RESPRAY LHS FRONT FENDER.	\$ 1,000.00	550 ✓
Parts			
1	FRONT LOCK CARRIER <i>Can L d</i>	\$ 1,400.00	✓ 1100
2	FRONT FENDER BRACE - LH <i>Best</i>	\$ 225.00	✓ 179.60
3	COOLANT <i>NA</i>	\$ 269.00	✓ 212.64
4	FRONT FENDER TOP LEDGE COVER - LH OUTER <i>NA</i>	\$ 31.00	✓ 24.64
GRAND TOTAL		\$ 6,925.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling

14/05/21

Sl.S.

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate - 2

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0350/2021/HR

17-May-21

CHANG

1 of 1

SMK 9638 P

QS SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	COOLANT HOSE WITH QUICK RELEASE COUPLING <i>Revised</i>	\$ 71.00	✓ 56.80
GRAND TOTAL		\$ 71.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling

17/05/21

[Signature]