

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0350/2021/HR
DATE : 22-Apr-21
WIP : 24194

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. VISHAL AGARWAL
ADDRESS : 78 BAYSHORE ROAD
#22-21
SINGAPORE 469991
TELEPHONE : HP +65 82016384
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SMK 9638 P**
MODEL CODE : Q5 SPORT 2.0 TFSI qu
MODEL YEAR : 30/4/2019
ENGINE NO : DAX 052277
CHASSIS NO : WAUZZZFY5K2044398
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Apr-21
PLACE OF ACCIDENT : NEAR 279 BALESTIER RD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 9638 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	250
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET, HINGES AND BOTH FRONT WHEEL ARCH TRIMS. //	\$ 4,000.00	1500 550 x 2 = 1100. Arch Trim x 2 = 400
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>7,872.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Reformed</i>	1	\$ 1,567.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 293.00	+
3	FRONT BUMPER SECURING STRIP - LH <i>3 new</i>	1	\$ 38.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH <i>cracked</i>	1	\$ 113.00	+✓
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 144.00	+
6	FRONT BUMPER SPOILER <i>new</i>	1	\$ 763.00	x
7	FRONT BUMPER UNDERRUN BAR <i>3 new</i>	1	\$ 518.00	+
8	FRONT BUMPER CLOSING ELEMENT	1	\$ 173.00	x
9	FRONT RADIATOR GRILLE <i>cracked</i>	1	\$ 3,530.00	✓
10	"QUATTRO" EMBLEM <i>new</i>	1	\$ 106.00	✓
11	FRONT RADIATOR STRIKER PLATE <i>cracked</i>	1	\$ 244.00	?✓
12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cracked</i>	1	\$ 581.00	✓
13	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH <i>cracked</i>	1	\$ 92.00	+✓
14	FRONT BUMPER LOCKING CLIP <i>new nec</i>	2	\$ 8.00	+✓
15	FRONT BUMPER FOAM FILLER PIECE <i>cracked</i>	1	\$ 177.00	+✓
16	FRONT BUMPER CARRIER <i>new</i>	1	\$ 981.00	f
17	FRONT BUMPER TOP COVER <i>cracked</i>	1	\$ 129.00	+✓
18	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	f
19	"CAUTION" STICKER <i>3 new</i>	1	\$ 14.00	+✓
20	AIR CONDITIONER STICKER	1	\$ 20.00	+✓
SUB TOTAL SPARE PARTS		:	\$ 9,510.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

S/N	PARTS DESCRIPTION	QTY		DAMAGED PAI	
				S/NETT	
21	FRONT HORN LOW TONE - LH	1	\$	195.00	+
22	FRONT INNER PARKING AID SENSOR	1	\$	244.00	+
23	FRONT OUTER PARKING AID SENSOR	1	\$	244.00	+
24	FRONT PARKING AID SENSOR SEAL RING	4	\$	14.00	+
25	FRONT BONNET <i>Dented</i>	1	\$	4,058.00	✓
26	FRONT BONNET LID HINGE - LH / RH	1	\$	322.00	+
27	FRONT BONNET ATTACHMENT PARTS	1	\$	141.00	+
28	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER	3	\$	84.00	✓
29	FRONT BONNET STRIKER	1	\$	240.00	+
30	FRONT BONNET LOCK	2	\$	427.00	+
31	FRONT BONNET BOWDEN CABLE - CENTER	1	\$	58.00	+
32	FRONT BONNET RELEASE ELEMENT nec	1	\$	58.00	+ ✓
33	FRONT BONNET RELEASE LEVER	1	\$	14.00	+
34	HEADLIGHT MOUNTING - LH / RH ? LH cracked	2	\$	236.00	? ✓ 118
35	HEADLIGHT - LH / RH <i>LH cracked</i>	2	\$	16,382.00	<i>8192</i>
36	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$	280.00	+
37	HEADLIGHT HOSE <i>new</i>	1	\$	125.00	+
38	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$	160.00	+
39	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$	1,264.00	✓
40	FRONT RADIATOR AIR GUIDE - LH <i>new</i> cracked	1	\$	58.00	+ ✓
TOTAL SPARE PARTS		:	\$	24,546.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT RADIATOR AIR GUIDE - UPPER / LOWER <i>2</i>	2	\$ 96.00	+
42	FRONT RADIATOR AIR GUIDE - CENTER <i>1</i>	1	\$ 42.00	+
3	FRONT NUMBER PLATE <i>New</i>	S/N	\$ 60.00	✓
44	SUNDRIES <i>?</i>		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 34,504.00	
TOTAL LABOUR CHARGES		:	\$ 7,872.00	
GRAND TOTAL		:	\$ 42,376.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE :
AUTHORISED DATE : ***
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT