

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0350/2021/HR
14-May-21
CHANG
1 of 1
SMK 9638 P
Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,800.00	1250.
3	TO REPAIR LHS FRONT FENDER.	\$ 800.00	550. X.
4	TO RESPRAY LHS FRONT FENDER.	\$ 1,000.00	550.
Parts			
1	FRONT LOCK CARRIER <i>could</i>	\$ 1,400.00	✓
2	FRONT FENDER BRACE - LH <i>Best</i>	\$ 225.00	✓
3	COOLANT <i>new</i>	\$ 269.00	✓
4	FRONT FENDER TOP LEDGE COVER - LH OUTER <i>NA</i>	\$ 31.00	✓
GRAND TOTAL		\$ 6,925.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
14/05/21
S.L.S.