

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

Veron

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0350/2021/HR
14-May-21
CHANG
1 of 1
SMK 9638 P
Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,800.00	1250.
3	TO REPAIR LHS FRONT FENDER.	\$ 800.00	550. X.
4	TO RESPRAY LHS FRONT FENDER.	\$ 1,000.00	550.
Parts			
1	FRONT LOCK CARRIER <i>could</i>	\$ 1,400.00	✓
2	FRONT FENDER BRACE - LH <i>Best</i>	\$ 225.00	✓
3	COOLANT <i>NA</i>	\$ 269.00	✓
4	FRONT FENDER TOP LEDGE COVER - LH OUTER <i>NA</i>	\$ 31.00	✓
GRAND TOTAL		\$ 6,925.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
14/05/21
S.L.S.

Car-in

11/5/21

mp = 24194

Kiam/Keong



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6541 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Aga Adnan

4 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Re-hom d</i>	1	\$ 1,567.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 293.00	+
3	FRONT BUMPER SECURING STRIP - LH <i>new</i>	1	\$ 38.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 113.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 144.00	+
6	FRONT BUMPER SPOILER <i>new</i>	1	\$ 763.00	x
7	FRONT BUMPER UNDERRUN BAR <i>new</i>	1	\$ 518.00	x
8	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 173.00	x
9	FRONT RADIATOR GRILLE <i>could</i>	1	\$ 3,530.00	✓
10	"QUATTRO" EMBLEM <i>new</i>	1	\$ 106.00	✓
11	FRONT RADIATOR STRIKER PLATE <i>could</i>	1	\$ 244.00	✓
12	FRONT BUMPER AIR GUIDE GRILLE - LH <i>could</i>	1	\$ 581.00	✓
13	FRONT BUMPER AIR GUIDE GRILLE END CAP - LH <i>could</i>	1	\$ 92.00	✓
14	FRONT BUMPER LOCKING CLIP <i>new</i>	2	\$ 8.00	✓
15	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 177.00	✓
16	FRONT BUMPER CARRIER <i>new</i>	1	\$ 981.00	+
17	FRONT BUMPER TOP COVER <i>could</i>	1	\$ 129.00	✓
18	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	+
19	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	✓
20	AIR CONDITIONER STICKER <i>new</i>	1	\$ 20.00	✓
SUB TOTAL SPARE PARTS			\$ 9,510.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 9638 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PAI S/NETT
21	FRONT HORN LOW TONE - LH	1 \$	195.00 +
22	FRONT INNER PARKING AID SENSOR	1 \$	244.00 +
23	FRONT OUTER PARKING AID SENSOR	1 \$	244.00 +
24	FRONT PARKING AID SENSOR SEAL RING	4 \$	14.00 +
25	FRONT BONNET <i>Dented</i>	1 \$	4,058.00 ✓
26	FRONT BONNET LID HINGE - LH / RH	1 \$	322.00 +
27	FRONT BONNET ATTACHMENT PARTS	1 \$	141.00 +
28	FRONT BONNET IMPACT PROTECTION - LH / RH / CENTER	3 \$	84.00 ✓
29	FRONT BONNET STRIKER	1 \$	240.00 +
30	FRONT BONNET LOCK	2 \$	427.00 +
31	FRONT BONNET BOWDEN CABLE - CENTER	1 \$	58.00 +
32	FRONT BONNET RELEASE ELEMENT	1 \$	58.00 ✓
33	FRONT BONNET RELEASE LEVER	1 \$	14.00 +
34	HEADLIGHT MOUNTING - LH / RH	2 \$	236.00 ✓
35	HEADLIGHT - LH / RH	2 \$	16,382.00 8192
36	HEADLIGHT LIFT CYLINDER - LH / RH	2 \$	280.00 +
37	HEADLIGHT HOSE	1 \$	125.00 +
38	FRONT WHEEL SPOILER - LH	1 \$	160.00 +
39	FRONT WHEEL ARCH COVER - LH / RH	2 \$	1,264.00 ✓
40	FRONT RADIATOR AIR GUIDE - LH	1 \$	58.00 ✓
TOTAL SPARE PARTS		:	\$ 24,546.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Lij
 17/05/21