

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 28 Jun 2021

Preliminary Advice

Vehicle No	: SMZ2346Z	Accident Date	: 22/04/2021
Make	: TOYOTA YARIS	Policy No.	: 29145565MCY
Assignment Date	: 26/04/2021	Excess	: S\$2,000.00
Date of Inspection	: 26/04/2021	Est. Duration of Repair	: 10
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,863.54
Revised Amount	:S\$	20,696.54
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,696.54

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	85,432.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,568.00

Remarks

- (X) The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair
- () The above survey was conducted on a 'without prejudice' basis.