

Code
 Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Borneo Motors (Singapore) Pte Ltd				
		Document No. 0	2 Pandan Crescent Inchcape Centre Singapore 128462				
		Document Date 23/04/2021	Work: 64751288				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	GXPA16R	AGFGZW R1	16/04/2021	SMZ2346Z	0	61636	65OD/SMZ2346Z
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDAF4E350A005685		G16E0011085	60	Francis Cher T S	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
10	B	BP-RES2 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. <i>0.550 Ltrs 10%</i>				<i>2655</i>	<i>3540.00</i>
11	1	T53811-52600 PANEL, FR FENDER, RH <i>bf</i>	1.00	728.00	15.00	<i>546</i>	<i>618.80</i>
12	2	T67001-59025 DOOR SUB-ASSY, RH <i>st</i>	1.00	2107.70	15.00	<i>1580</i>	<i>1791.54</i>
13	3	T90269-06013 RIVETS <i>re</i>	4.00	1.90	15.00	<i>5.68</i>	<i>6.44</i>
14	4	T75851-52904 MOULDING, BODY <i>de</i>	1.00	716.60	15.00	<i>537.45</i>	<i>609.11</i>
15	5	T42611-52D00 WHEEL, DISC <i>scd</i>	1.00	11331.30	15.00	<i>8498.45</i>	<i>9631.60</i>
16	6	T61601-52730 PANEL SUB-ASSY, <i>torn</i>	1.00	1258.20	15.00	<i>943.65</i>	<i>1069.47</i>
17	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>re</i>	1.00	108.00	15.00	<i>81</i>	<i>91.80</i>
18	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>re</i>	1.00	200.00	15.00	<i>150</i>	<i>170.00</i>
19	9	T08826-08115 PANEL BONDING AD <i>re</i>	1.00	267.20	15.00	<i>200.40</i>	<i>227.12</i>
20	0	T62710-52320 WINDOW ASSY, <i>nec</i>	1.00	692.70	15.00	<i>519.52</i>	<i>588.79</i>
21	1	T75361-52110 PLATE, FR FENDER <i>re</i>	1.00	416.80	15.00	<i>312.60</i>	<i>354.28</i>
22	2	T53875-52540 LINER, FR FENDER, RH <i>? x3m</i>	1.00	240.70	15.00		<i>204.59</i>
						<i>20696.54</i>	

Repair
4p 90010068
10 days
26/04/21
1450
EXCESS: TBA
Revert
Reay before print

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from insurance company

Acknowledged by Repairer

Signature: _____

Date: _____

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature Please acknowledge receipt of vehicle	Charge Summary	Total
		Parts 15,363.54	24,863.54
		Labour 9,460.00	
		Sublet 40.00	
		Lubrication/Fluid 0.00	
		Others 0.00	
		GST 7.00%	1,740.45
		Less	0.00
		Amount Due	26,603.99

Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000004 / ICCUA1	M/S Borneo Motors (Singapore) Pte Ltd 2 Pandan Crescent Inchcape Centre Singapore 128462
	Document No. 0	Work: 64751288
	Document Date 23/04/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	GXPA16R	AGFGZW R1	16/04/2021	SMZ2346Z	0	61636	65OD/SMZ2346Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDAF4E350A005685	G16E0011085	60	Francis Cher T S	---/---/---	0.00 ---/---/---

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE:22.04.21 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				60.00
3	B	BP-LAB2 CHK WIRING SYSTEM AND CONDUCT WATER TEST.				162 180.00
4	B	BP-LAB2 REMOVE R/F DOOR COMPONENTS TO TRANSFER ONTO NEW DOOR.				324 360.00
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				162 180.00
6	B	BP-MECH2 CONDUCT WHEEL ALIGNMENT.				324 360.00
7	S	BP-SUBLET REPLACE AND BALANCE R/F RIM				40.00
8	B	BP-LAB2 REPLACE R/R 1/4 GLASS.				324 360.00
9	B	BP-LAB2 REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN FRT BUMPER, R/F FENDER, R/F DOOR, R/R FENDER, R/SIDE SKIRTING AND AFFECTED PORTION OF CAR.				324 4320.00

@720 hrs 10%

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due