

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pang Xiu Shi

Date: 27 Apr 2021

**Preliminary Advice**

Vehicle No	: SMZ2346Z	Accident Date	: 22/04/2021
Make	: TOYOTA YARIS	Policy No.	: 29145565MCY
Assignment Date	: 26/04/2021	Excess	: S\$2,000.00
Date of Inspection	: 26/04/2021	Est. Duration of Repair	: 10
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,863.54
Revised Amount	:S\$	22,035.16
Check Items (Estimated)	:S\$	793.38
Total	:S\$	22,828.54

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	85,432.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,568.00

**Remarks**

- ( X ) The vehicle is economical for repair  
( ) The vehicle is not economical for repair  
( ) Part-by-Part repair  
( ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.