



Champion Motors

Inchcape

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



ACCOUNT INVOICE

Account Details			Account No.		Customer Details		
MSIG Insurance (S) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building			S8000033 / WIIC2		Mdm Koh Hwee Boon Doris 2 Lentor Link Singapore 786734 Mobile: 98002778		
			Document No. 82001994				
			Document Date 20/11/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	28420	12046	72/OD/SMV9422L
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JSAGJB74V00137038		K15B1063232	60	Thomas Pang W T	26/04/2021 9.39		20/11/2021 8.23
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	S	S-BMS SUNDRIES POLICY:A29147606AS2 ACC DATE:24.04.2021 TOW IN:24.04.2021 EXCESS:\$500 DATE IN:26.04.2021 DATE SURVEY:26.04.2021 NO REPAIR DAYS:07 WORKING DAYS BY:LKK-RASUL AUTHORISED:27.04.2021		50.00		50.00	
2	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST		99.62	10.00	89.66	
3	S	S-BMS TO CONDUCT FULL WHEEL ALIGNMENT		146.50	10.00	131.85	
4	S	S-BMS TO CONDUCT ADJUSTMENT ON FRONT RADAR SENSORS		146.50	10.00	131.85	
5	S	S-BMS REPLACE RIM AND WHEEL BALANCING	0239	117.20		117.20	
6	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS		1172.00	10.00	1054.80	
7	S	S-BMS RESPRAY ACC AFFECTED AREAS		1452.00	10.00	1306.80	
8	S	S-EURO-001 SUPPLY NUMBER PLATE	0263	80.00		80.00	
9	V	EXC Excess element of insurance repair to be paid by the insured party	8888	500.00		-500.00	
10	1	S35100-77RA0-000 HEADLAMP ASSY,R	1.00	1183.00	25.00	887.25	
11	2	S43210-78R01-0BK WHEEL,AL(15X5 1/2J)	2.00	544.40	25.00	816.60	
For & on behalf of Champion Motors (1975) Pte Ltd			Customer's Signature		Charge Summary		Total
					Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
			Others		Amount Due		

Customer Copy