

Reg No. : 195000068E
 Reg No. : MR-8500000-9
 Pandan Crescent
 Singapore 128462 Tel: 66311855

ESTIMATE

Account Details			Account No.		Customer Details		
Service Retail Cash Sales Body & Paint Service Retail Cash Sales Body & Paint			c0199882 / SERVCASH		Mdm Koh Hwee Boon Doris		
			Document No. 0		2 Lontor Link		
			Document Date 26/04/2021		Singapore 766734 Mobile: 98002778		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	0	12046	72/OD/SMV9422L
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JSAGJB74V00137038		K15B1063232	00	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	S	S-BMS SUNDRIES POLICY:A29147606AS2 ACC DATE:24.04.2021 TOW IN:24.04.2021 EXCESS: DATE IN:26.04.2021 DATE SURVEY: NO REPAIR DAYS: BY: AUTHORIZED:		50.00		50.00	
2	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST		99.62	10.00	89.66	
3	S	S-BMS TO CONDUCT FULL WHEEL ALIGNMENT		146.50	10.00	131.85	
4	S	S-BMS TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR		146.50	10.00	131.85	
5	S	S-BMS REPLACE RIM AND WHEEL BALANCING		117.20		117.20	
6	S	S-BMS SUPPLY LH FRONT TYRE <i>cut 7.2w = 266</i>		380.00		380.00	
7	S	S-BMS REPLACE FRONT UNDERCARRIAGE		1172.00	10.00	1054.80	
8	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS <i>527.40</i>		2930.00	10.00	2637.00	
9	S	S-BMS RESPRAY ACC AFFECTED AREAS <i>9435.60</i>		2420.00	10.00	2178.00	
10	S	S-EURO-001 SUPPLY NUMBER PLATE <i>80.00</i>		80.00		80.00	
11	1	S35100-77RA0-000 HEADLAMP ASSY,R <i>CM</i>	1.00	1183.00	25.00	887.25	
12	2	S35300-77RA0-000 HEADLAMP ASSY,L <i>XSVC</i>	1.00	1183.00	25.00	887.25	
For & on behalf of Champion Motors (1975) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Reg No. : 195000068E
 Reg No. : MR-8500000-9
 Pandan Crescent
 Singapore 128462 Tel: 66311855

ESTIMATE

Account Details		Account No.	Customer Details				
Service Retail Cash Sales Body & Paint		c0199882 / SERVCASH	Mdm Koh Hwee Boon Doris				
Service Retail Cash Sales Body & Paint		Document No.	2 Lantor Link				
		0	Singapore 786734				
		Document Date	Mobile: 98002778				
26/04/2021							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	0	12046	72/OD/SMV9422L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JSAGJB74V00137038	K15B1063232	00	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	3	S35500-54P00-000 LAMP ASSY,FOG AND DRL ? xsv	2.00	206.25	25.00	309.38	
14	4	S35526-78R00-000 BRACKET,FOG LAMP,R ? xsv	1.00	34.55	25.00	25.91	
15	5	S35566-78R00-000 BRACKET,FOG LAMP,L ? xsv	1.00	34.55	25.00	25.91	
16	6	S45200-77R00-000 ARM ASSY,FR LEADING ? xsv	2.00	379.50	25.00	569.24	
17	7	S45300-77R00-000 ROD ASSY,FR LATERAL ? xsv	1.00	96.85	25.00	72.64	
18	8	S41610-78R00-000 ABSORBER,FR SHOCK ? xsv	2.00	190.55	25.00	285.82	
19	9	S42311-77R00-000 BAR,FR STABILIZER ? xsv	1.00	195.80	25.00	146.85	
20	0	S45111-78R00-000 KNUCKLE,STRG,R ? xsv	1.00	314.10	25.00	235.57	
21	1	S45151-78R00-000 KNUCKLE,STRG,L ? xsv	1.00	342.90	25.00	257.17	
22	2	S44101-78R00-000 JOINT ASSY,FR AXLE SHAFT,R ? xsv	1.00	628.15	25.00	471.11	
23	3	S44102-78R00-000 JOINT ASSY,FR AXLE SHAFT,L ? xsv	1.00	628.15	25.00	471.11	
24	4	S43420-76840-000 HUB SET,FR WHL ? xsv	2.00	163.85	25.00	245.78	
25	5	S43440-81A20-000 SPINDLE,FR WHEEL,R ? xsv	1.00	228.75	25.00	171.56	
26	6	S43440-81A30-000 SPINDLE,FR WHEEL,L ? xsv	1.00	228.75	25.00	171.56	
27	7	S43462-84A00-000 BEARING,FR WHEEL ? xsv	2.00	124.60	25.00	186.90	
28	8	S43810-76J02-000 HUB ASSY,AIR LOCKING ? xsv	2.00	492.05	25.00	738.08	
29	9	S45500-78R00-000 HOUSING,FR AXLE ? xsv	1.00	1219.65	25.00	914.74	
30	0	S43210-78R01-0BK WHEEL,AL(15X5 1/2J) ? xsv	2 x 1.00	544.40	25.00	816.60	1224.90
31	1	S48600-78R00-000 BOX ASSY,STRG GEAR ? xsv	1.00	1397.65	25.00	1048.24	
32	2	S48931-78R10-000 ROD,STRG DRAG ? xsv	1.00	126.20	25.00	94.65	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Champion Motors (1975) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy

No. : 195000068E
 No. : MR-8500000-9
 Pandan Crescent
 Singapore 128462 Tel: 66311855

ESTIMATE

Account Details		Account No.	Customer Details	
Service Retail Cash Sales Body & Paint		c0199882 / SERVCASH	Mdm Koh Hwee Boon Doris	
Service Retail Cash Sales Body & Paint		Document No. 0	2 Lantor Link	
		Document Date 26/04/2021	Singapore 786734	
			Mobile: 98002778	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	0	12046	72/OD/SMV9422L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JSAGJB74V00137038	K15B1063232	00	Thomas Pang W T	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
33	3	S48820-78R10-000 END,ROD <i>? xsv</i>	1.00	154.95	25.00	116.21
34	4	S48810-78R00-000 END,ROD <i>? xsv</i>	1.00	62.85	25.00	47.14
35	5	S48831-78R10-000 TIE-ROD,STRG <i>? xsv</i>	1.00	167.00	25.00	125.25
36	6	S48820-78R00-000 END,ROD <i>? xsv</i>	1.00	62.85	25.00	47.14
37	7	S48810-78R00-000 END,ROD <i>? xsv</i>	1.00	62.85	25.00	47.14
38	8	S58110-78R00-000 MEMBER COMP,1ST MOUNT <i>? xsv</i>	1.00	52.35	25.00	39.26
39	9	S58130-78R00-000 PANEL COMP,1ST MOUNT,R <i>? xsv</i>	1.00	94.25	25.00	70.69
40	0	S58146-78R00-000 BRACKET,FR OUTER PANEL LWR,R <i>? xsv</i>	1.00	3.70	25.00	2.77
41	1	S58150-78R00-000 PANEL COMP,1ST MOUNT,L <i>? xsv</i>	1.00	94.25	25.00	70.69
42	2	S58166-78R00-000 BRACKET,FR OUTER PANEL LWR,L <i>? xsv</i>	1.00	3.70	25.00	2.77
43	3	S58172-78R00-000 BRACKET,FR OUTER PANEL UPR,R <i>? xsv</i>	1.00	7.90	25.00	5.92
44	4	S58200-78R00-000 PANEL,FR OUTER <i>? xsv</i>	1.00	481.60	25.00	361.20
45	5	S72371-78R00-000 COVER,FRONT PANEL UPR <i>? xsv</i>	1.00	9.95	25.00	7.46
46	6	S72381-78R00-000 SHROUD,RADIATOR UPR <i>? xsv</i>	1.00	57.60	25.00	43.20
47	7	S72391-78R00-000 PROTECTOR,FRONT PANEL LWR,R <i>? xsv</i>	1.00	7.90	25.00	5.92
48	8	S72392-78R00-000 PROTECTOR,FRONT PANEL LWR,L <i>? xsv</i>	1.00	7.90	25.00	5.92
49	9	S09409-07340-000 CLIP <i>? new</i>	10.00	2.05	25.00	15.40
50	0	S58611-78R00-000 PANEL,FR FENDER,R <i>bt</i>	1.00	136.10	25.00	102.07
51	1	S72320-78R00-000 LINING COMP,FRONT FENDER,R <i>? torn</i>	1.00	47.15	25.00	35.36
52	2	S72334-78R00-000 HOLDER,COWL SIDE <i>? xsv</i>	1.00	4.20	25.00	3.15

For & on behalf of	Customer's Signature	Charge Summary	Total
Champion Motors (1975) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Less
			Amount Due

Customer Copy

No. : 195000068E
 No. : MR-8500000-9
 Andan Crescent
 Pore 128462 Tel: 66311855

ESTIMATE

Account Details			Account No.		Customer Details		
Service Retail Cash Sales Body & Paint Service Retail Cash Sales Body & Paint			c0199882 / SERVCASH		Mdm Koh Hwee Boon Doris		
			Document No. 0		2 Lontor Link		
			Document Date 26/04/2021		Singapore 786734 Mobile: 98002778		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	0	12046	72/OD/SMV9422L
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JSAGJB74V00137038		K15B1063232	00	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
53	3	S09409-07340-000	CLIP ? ne /	10.00	2.05	25.00	15.40
54	4	S71711-78R10-5PK	BUMPER,FRONT de /	1.00	429.25	25.00	321.94
55	5	S71713-78R00-5PK	GARNISH,FR BPR LICENSE(BLACK) ? xsr	1.00	37.70	25.00	28.27
56	6	S71721-78R00-5PK	NET,FRONT BUMPER ? xsr	1.00	33.00	25.00	24.75
57	7	S71741-78R00-000	SKIRT,FR AIR DAM ? xsr	1.00	25.15	25.00	18.86
58	8	S72110-78R00-C48	GRILLE COMP,RADIATOR cm -	1.00	298.40	25.00	223.80
59	9	S77511-78R00-5PK	GUARD,FR FND R SPLASH,R(BLACK) xsr	1.00	102.10	25.00	76.57
60	0	S77512-78R00-000	PROTECTOR,FR FENDER SPLASH ne /	1.00	19.40	25.00	14.55
61	1	S09409-10312-000	CLIP ne /	10.00	1.60	25.00	12.00
62	2	S77521-78R00-5PK	GUARD,FR FND R SPLASH,L(BLACK) ? xsr	1.00	102.10	25.00	76.57
63	3	S77512-78R00-000	PROTECTOR,FR FENDER SPLASH ? xsr	1.00	19.40	25.00	14.55
64	4	S77531-78R00-5PK	GUARD,RR FND R SPLASH,R(BLACK) xsr	1.00	107.35	25.00	80.51
65	5	S77532-78R00-000	PROTECTOR,RR FENDER SPLASH ne /	1.00	19.90	25.00	14.92
66	6	S09409-10318-000	CLIP ne /	10.00	1.80	25.00	13.50
67	7	S77550-78R00-5PK	GUARD ASSY,SIDE SILL SPLASH,R ? xsr	1.00	109.95	25.00	82.46
68	8	S77552-78R00-000	PROTECTOR,SIDE SILL SPLASH ? xsr	1.00	13.65	25.00	10.24
69	9	S84701-77R20-ZJ3	MIRROR ASSY,RR VIEW,R(BLACK) ? xsr	1.00	237.15	25.00	177.86

Handwritten notes:
 Resur
 Hp 90010068
 7 days
 26/04/21 @ 1520
 excess 500
 Revers
 Reamry
 before
 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

For & on behalf of		Charge Summary	Total
Champion Motors	Customer's Signature		18,653.39
(1975) Pte Ltd 100, Telok Ayer St, Singapore 068563 Tel: 6733 8888 Fax: 6733 8889 Email: info@championmotors.com.sg Website: www.championmotors.com.sg		Parts	11,803.03
		Labour	0.00
		Sublet	6,850.36
		Lubrication/Fluid	0.00
		Others	0.00
		GST 7.00%	1,305.74
		Less	0.00
		Amount Due	19,959.13

Customer Copy