



Champion Motors

Inchcape

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



ESTIMATE

Account Details			Account No.		Customer Details			
MSIG Insurance (S) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building			S8000033 / WIIC2		Mdm Koh Hwee Boon Doris 2 Lentor Link Singapore 786734 Mobile: 98002778			
			Document No. 0					
			Document Date 04/05/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	2036	12046	72/OD/SMV9422L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JSAGJB74V00137038		K15B1063232	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	S	S-BMS SUNDRIES POLICY:A29147606AS2 ACC DATE:24.04.2021 TOW IN:24.04.2021 EXCESS:\$500 DATE IN:26.04.2021 DATE SURVEY:26.04.2021 NO REPAIR DAYS:07 WORKING DAYS BY:LKK-RASUL AUTHORISED:27.04.2021				50.00		50.00
2	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST				99.62	10.00	89.66
3	S	S-BMS TO CONDUCT FULL WHEEL ALIGNMENT				146.50	10.00	131.85
4	S	S-BMS TO CONDUCT ADJUSTMENT ON FRONT RADAR SEN SOR				146.50	10.00	131.85
5	S	S-BMS REPLACE RIM AND WHEEL BALANCING			0239	117.20		117.20
6	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1172.00	10.00	1054.80
7	S	S-BMS RESPRAY ACC AFFECTED AREAS				1452.00	10.00	1306.80
8	S	S-EURO-001 SUPPLY NUMBER PLATE			0263	80.00		80.00
9	V	EXC Excess element of insurance repair to be paidby the insured party			8888	500.00		-500.00
10	1	S35100-77RA0-000 HEADLAMP ASSY,R			1.00	1183.00	25.00	887.25
11	2	S43210-78R01-0BK WHEEL,AL(15X5 1/2J)			2.00	544.40	25.00	816.60
For & on behalf of Champion Motors (1975) Pte Ltd		Customer's Signature		Charge Summary		Total Less Amount Due		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others				

Company Copy



Champion Motors

Inchcape

Co. Reg No. : 195000068E
GST Reg No. : MR-8500000-9
No. 2 Pandan Crescent
Singapore 128462 Tel: 66311855



ESTIMATE

Account Details			Account No.		Customer Details			
MSIG Insurance (S) Pte Ltd 16 Raffles Quay #24-01 Hong Leong Building			S8000033 / WIIC2		Mdm Koh Hwee Boon Doris 2 Lantor Link Singapore 786734 Mobile: 98002778			
			Document No. 0					
			Document Date 04/05/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	JIMNY	6GG1BHH35	28/10/2020	SMV9422L	2036	12046	72/OD/SMV9422L	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JSAGJB74V00137038		K15B1063232	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
12	3	S58200-78R00-000 PANEL,FR OUTER			1.00	481.60	25.00	361.20
13	4	S09409-07340-000 CLIP			10.00	2.05	25.00	15.40
14	5	S58611-78R00-000 PANEL,FR FENDER,R			1.00	136.10	25.00	102.07
15	6	S72320-78R00-000 LINING COMP,FRONT FENDER,R			1.00	47.15	25.00	35.36
16	7	S09409-07340-000 CLIP			10.00	2.05	25.00	15.40
17	8	S71711-78R10-5PK BUMPER,FRONT			1.00	429.25	25.00	321.94
18	9	S72110-78R00-C48 GRILLE COMP,RADIATOR			1.00	298.40	25.00	223.80
19	0	S77511-78R00-5PK GUARD,FR FNDR SPLASH,R(BLACK)			1.00	102.10	25.00	76.57
20	1	S77512-78R00-000 PROTECTOR,FR FENDER SPLASH			1.00	19.40	25.00	14.55
21	2	S09409-10312-000 CLIP			9.00	1.60	25.00	10.80
22	3	S77531-78R00-5PK GUARD,RR FNDR SPLASH,R(BLACK)			1.00	107.35	25.00	80.51
23	4	S77532-78R00-000 PROTECTOR,RR FENDER SPLASH			1.00	19.90	25.00	14.92
24	5	S09409-10318-000 CLIP			10.00	1.80	25.00	13.50
25	6	S09409-10312-000 CLIP			1.00	1.60	25.00	1.20
26	7	YTDAT1-9580R 15 DUNLOP AT20 195/80R15			1.00	380.00	30.00	266.00
For & on behalf of Champion Motors (1975) Pte Ltd			Customer's Signature		Charge Summary		Total 5,719.23	
					Parts 3,257.07		GST 7.00% 400.35	
					Labour 0.00		Less 0.00	
					Sublet 2,962.16			
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 6,119.58	

Company Copy