



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Adrian Lee
u09

26/04/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP u01
Veron.

Accident date: 20.04.2021

Estimated repair cost for vehicle no: SJQ7940H TOYOTA ALTIS 1.6 A '09

CHASSIS: MR053ZEE106145757

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Bumper <i>for</i>		\$561.85
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
3	1	Front Bumper Emblem Logo <i>new</i>		\$61.75
4	1	Front Bumper Reinforcement <i>new</i>		\$374.40 <i>x</i>
5	1	Front L/H Bumper Side Retainer <i>new</i>		\$122.10 <i>45</i>
6	1	Front L/H Bumper Fog Lamp <i>new</i>		\$374.10 <i>+</i>
7	1	Front L/H Bumper Fog Lamp Cover <i>new</i>		\$174.40 <i>+</i>
8	1	Front L/H Head Lamp <i>cut</i>		\$378.85
9	1	Front L/H Fender <i>Dented</i>		\$374.10 <i>✓</i>
10	1	Front L/H Fender Cowling <i>for</i>		\$182.10
11	10	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 <i>20</i>
12	1	Front L/H Rim (Special Nett) <i>cut</i>		\$680.00 <i>450(SN)</i>
13	1	Front L/H Tyre (Special Nett) <i>new</i>		\$350.00 <i>x</i>
14	1	Front L/H Lower Arm <i>Bent</i>		\$581.90 <i>375</i>
15	1	Front L/H Knuckle Arm <i>Bent</i>		\$561.60 <i>472</i>
16	1	Front L/H Knuckle Arm Bearing <i>Bent</i>		\$191.80 <i>✓</i>
17	1	Front L/H Shock Absorber <i>new</i>		\$381.90 <i>+</i>
18	1	Front L/H Drive Shaft <i>new</i>		\$1,712.40 <i>x</i>
19	1	Front Steering Rack <i>new</i>		\$1,822.50 <i>x</i>
20	1	Front L/H Door <i>Dented</i>		\$1,168.30 <i>✓</i>
21	2	Front L/H Door Hinge <i>new</i>	\$54.00	\$108.00 <i>x</i>
22	2	Front L/H Door Frame Sticker <i>new</i>	\$58.80	\$117.60 <i>✓</i>
23	1	Front L/H Door Weatherstrip <i>new</i>		\$162.80 <i>+</i>
24	1	Front L/H Door Lower Chrome Moulding <i>cut</i>		\$148.35 <i>✓</i>
25	1	Front L/H Door Side Mirror Assy <i>Dented</i>		\$525.65 <i>✓</i>
26	1	L/H Side Skirt <i>Dented</i>		\$385.00 <i>✓</i>
27	1	L/H Rocker Panel <i>Rep</i>		\$424.00 <i>x</i>

5037.35 S.N. 460 Subtotal: \$12,055.45

3718.01

Labour charges

To remove & refit front L/H undercarriage & steering rack

~~\$380.00~~ 220

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

2150

~~\$150.00~~ 60

Towing fee

~~\$150.00~~ 60

Panel beating

~~\$1,600.00~~ 800

Spray painting

~~\$1,400.00~~ 900

Subtotal:- \$3,930.00

Total:- \$15,985.45

Adrian L

w/s 26/04/21.

06 Days.

total: 16378.01

f/s: SIK

SIK
SIK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: