

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 29 Apr 2021

Preliminary Advice

Insured Vehicle No	: SLN9851K		
TP Vehicle No	: SGJ9666J	Accident Date	: 22/04/2021
Make	: TOYOTA ALPHARD	Assignment Date	: 28/04/2021
Date of Inspection	: 27/04/2021	Est. Duration of Repair	: 18
Inspection At	: STARS AUTOWORKS (HQ) 160 SIN MING DRIVE, #06-21 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,104.28
Revised Amount	:S\$	11,976.88
Check Items (Estimated)	:S\$	6,268.68
Total	:S\$	18,245.56

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.