



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21005117/Atf3e2	
			Date: 31/05/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 8304R	Veh. Inspected	GBD 612P	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D12662105	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	26/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2184	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	CR425009696	Colour	SILVER	
Odometer	352984 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165 R13	DUNLOP	6 mm	
L/H Front Tyre	165 R13	DUNLOP	6 mm	
R/H Rear Tyre	165 R13	DUNLOP	6 mm	
L/H Rear Tyre	165 R13	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/04/2021	Inspection Date	26/04/2021	
Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	