

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000037 / ICCUA2	Mdm Siti Nur Aishah Binte Kamil 432A Yishun Avenue 1 #10-517 Singapore 761432 Mobile: 90625045				
		Document No. 0					
		Document Date 24/04/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	22/03/2018	SLX2656B	0	61653	72/OD/SLX2656B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDGG20W50J008857	2ZR0A56490	60	Thomas Pang W T	--/--/----		0.00	--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: A29149972ATM ACC DATE: 23.04.2021 DRIVE IN: 24.04.2021 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100 200 200.00	
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				110.16	
4	B	BP-MECH2 R/I AC CONDENSOR, PIPING AND REGAS				324.00	
5	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				162.00	
7	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				3240 1944 3240.00	
8	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				3186 265 317.00	
9	1	T52119-68909 FRONT BUMPER COVER, de	1.00	591.80	25.00	443.85	
10	2	T52115-68031 R/FRT BUMPER SUPPORT, neu	1.00	62.80	25.00	47.10	
11	3	T52116-68031 L/FRT BUMPER SUPPORT, neu	1.00	62.80	25.00	47.10	
12	4	T52611-68030 FRT BUMPER ABSORBER, neu	1.00	101.90	25.00	76.42	
13	5	T52021-68020 F/BPR REINFORCEMENT, neu	1.00	305.20	25.00	228.90	
For & on behalf of		Customer's Signature	Charge Summary			Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts			Less	
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others			Amount Due	

Company Copy

Borneo Motors



Reg No. : 196700086Z
 ST Reg No. : MR-8500000-9
 No 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6531 1188

ESTIMATE

Account Details	Account No.	Customer Details
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	Mdm Siti Nur Aishah Binte Kamil 432A Yishun Avenue 1 #10-517 Singapore 761432 Mobile: 90625045
	Document No. 0	
	Document Date 24/04/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZGE20R	HPXNP S6	22/03/2018	SLX2656B	0	61653	72/OD/SLX2656B
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W50J008857	2ZR0A56490	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	6	T52030-68010 R/F BUMPER HOLE COVER, <i>can Xsrc</i>	1.00	85.50	25.00	64.12
15	7	T53112-68030 F/LOW RADIATOR GRILLE, <i>can Xsrc</i>	1.00	57.00	25.00	42.75
16	8	T53119-68010 FRT GRILLE PROTECTOR, <i>can Xsrc</i>	1.00	29.40	25.00	22.05
17	9	T52040-68010 L/F BUMPER HOLE COVER, <i>can Xsrc</i>	1.00	85.50	25.00	64.12
18	0	T53113-68010 L/F LWR RADIATOR GRILLE, <i>can Xsrc</i>	1.00	57.00	25.00	42.75
19	1	T53149-68010 PROTECTOR RADIATOR, <i>can Xsrc</i>	1.00	32.40	25.00	24.30
20	2	T53101-68010 GRILLE SUB-ASSY, <i>can Xsrc</i>	1.00	415.10	25.00	311.32
21	3	S52161-0K040 PIECE,RR BUMPER, <i>can Xsrc</i>	10.00	4.10	25.00	30.70
22	4	T53301-68020 FRONT BONNET ASSY, <i>can Xsrc</i>	1.00	977.80	25.00	733.35
23	5	T53381-68020 FRONT BONNET SEAL, <i>can Xsrc</i>	1.00	32.70	25.00	24.52
24	6	T90467-09050 CLIP, <i>can Xsrc</i>	1.00	2.90	25.00	2.17
25	7	T53812-68060 FENDER SUB-ASSY,LH, <i>repair</i>	1.00	988.40	25.00	741.30
26	8	T53510-68050 FRONT BONNET LOCK, <i>Xsrc</i>	1.00	93.20	25.00	69.90
27	9	T53410-68030 R/FRT BONNET HINGE, <i>bt</i>	1.00	58.90	25.00	44.17
28	0	T53420-68030 L/FRT BONNET HINGE, <i>bt</i>	1.00	58.90	25.00	44.17
29	1	T53292-68020 F/UPPER RADIATOR SEAL, <i>? Xnn</i>	1.00	93.20	25.00	69.90
30	2	T90467-07217 CLIP, <i>? Xnn</i>	10.00	2.50	25.00	18.70
31	3	T53208-68020 F/BRACE LOCK SUPPORT, <i>bt support head lock</i>	1.00	93.20	25.00	69.90
32	4	T53201-68021 FRT RADIATOR SUPPORT, <i>bt support sub Assy</i>	1.00	1484.50	25.00	1113.37
33	5	T90975-02086 TOYOTA SYMBOL EMBLEM, <i>can Xsrc</i>	1.00	72.20	25.00	54.15

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy



No. : 196700086Z
 Reg No. : MR-8500000-9
 PANDAN CRESCENT
 SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details						
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000037 / ICCUA2	Mdm Siti Nur Aishah Binte Kamil 432A Yishun Avenue 1 #10-517 Singapore 761432 Mobile: 90625045						
		Document No. 0							
		Document Date 24/04/2021							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZGE20R	HPXNP S6	22/03/2018	SLX2656B	0	61653	72/OD/SLX2656B		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDGG20W50J008857		2ZR0A56490	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
34	6	T81145-68100	UNIT, HEADLAMP ? <i>750</i>			1.00	1265.70	25.00	949.27
35	7	T81185-68100	UNIT, HEADLAMP LH ? <i>750</i>			1.00	1265.70	25.00	949.27
36	8	T81210-47010	R/FRONT FOG LAMP ASSY <i>750</i>			1.00	310.40	25.00	232.80
37	9	T81220-47010	LAMP ASSY, FOG, LH ? <i>750</i>			1.00	295.20	25.00	221.40
38	0	T88450-12280	A/C CONDENSER ASSY. ? <i>750</i>			1.00	1801.70	25.00	1351.27
39	1	S08889-80102	COOLANT, SLLC&& ? <i>750</i>			2.00	79.50	25.00	59.62
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					<i>7 days</i> <i>26/04/21 @ 15:30</i> <i>EXCESS: 500</i> <i>Revert</i> <i>Resurvey before paint</i>				
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total			
Please acknowledge receipt of vehicle				Parts	8,254.33	GST 7.00%		1,129.62	
				Labour	7,803.16	Less		0.00	
				Sublet	80.00				
				Lubrication/Fluid	0.00				
				Others	0.00	Amount Due		17,267.11	