

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 27 Apr 2021

Preliminary Advice

Vehicle No	: SLX2656B	Accident Date	: 23/04/2021
Make	: TOYOTA WISH	Policy No.	: 29149972ATM
Assignment Date	: 26/04/2021	Excess	: S\$500.00
Date of Inspection	: 26/04/2021	Est. Duration of Repair	: 7
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,137.49
Revised Amount	:S\$	6,967.83
Check Items (Estimated)	:S\$	4,378.27
Total	:S\$	11,346.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	44,149.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,851.00

Remarks

- (X) The vehicle is economical for repair
() The vehicle is not economical for repair
() Part-by-Part repair
() Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.