

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21005119/NVF3E2

Date: 07/05/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	ML000510		
Claimant Vehicle No :	SHB6640H	Insured Vehicle No :	SMY3768M		
Date of Loss:	23/04/2021	Nature of Claim:	TP	Claim No:	M2102015

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6640H	Engine No:	G4LEJU193660
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU141794
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	188499 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,357.24	1,316.68	2,040.56	60.78
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,180.00	1,615.00	565.00	25.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,548.24	2,942.68	2,605.56	46.96
+ GST 7.00/7.00% (S\$)	388.38	205.99	182.39	46.96
Nett Amount (S\$)	5,936.62	3,148.67	2,787.95	46.96

INSPECTION

Date of Assignment:	26/04/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	26/04/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2021)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6640H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER	Cracked	430.90 FL	-	*430.90 FL
2	1		*FRT FENDER LH	Repair	588.80 FL	-	*- FL
3	1		*FRT FENDER SHIELD LH	Serviceable	164.70 FL	-	*- FL
4	1		*FRT FENDER BLUE-DRIVE LH	Necessary	26.60 FL	-	*26.60 FL
5	1		*FRT DOOR LH	Repair	1,797.20 FL	-	*- FL
6	1		*FRT DOOR LOWER PROTECTOR LH	Scratched	186.20 FL	-	*186.20 FL
7	1		*ROCKER PANEL GARNISH LH	Deformed	290.00 FL	-	*290.00 FL
8	1		*FRT WHEEL CAP LH	Scratched	346.40 FL	-	*346.40 FL
9	1		*FRT FENDER ADVERTISEMENT STICKER LH	Necessary	100.00 F	-	*100.00 F
10	1		*FRT DOOR ADVERTISEMENT STICKER LH	Necessary	100.00 F	-	*100.00 F
11	1		*FRT DOOR COMFORTDELGRO LH	Necessary	75.00 F	-	*75.00 F
12	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,127.80	1,577.10
- List Item Discount on L Items 20.00/20.00% (\$)	770.56	260.42
Total Parts (\$)	3,357.24	1,316.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING	New	1,200.00	875.00
3	TUFF KOTE	New	60.00	40.00
4	TRANSFER OF DOOR	New	120.00	0.00
Gross Labour Cost (\$\$)			2,180.00	1,615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >