

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

23-Apr-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1485 L

S/NETT

1 pc	Front o/s fender sticker	\$	30.00	NEC
	Sundry	\$	50.00	XNN
	To check wheel alignment	\$	80.00	XNN
	To focus/check front n/s & o/s head lamps	\$	60.00	XNN
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	600.00	360
	To putty and spray painting on front bumper, front o/s fender	\$	400.00	360
	To apply rustproofing on the repaired and replaced panels.	\$	80.00	40
		\$	<u>1,300.00</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.**

NA2 CLK

26/4/2021 1700

L/S

2 DAYS

AFTER REPAIR PHOTOS

S/NETT \$ 30.00
LABOUR \$ 760.00
TOTAL \$ 790.00 / 2 REPAIR DAYS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: