

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21005122/NVF3E2

Date: 07/05/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR000127		
Claimant Vehicle No :	SH8998B	Insured Vehicle No :	SKJ8623S		
Date of Loss:	23/04/2021	Nature of Claim:	TP	Claim No:	M2102025

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8998B	Engine No:	2ZRS055801
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKB3FU303561256
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	425479 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,501.57	916.05	585.52	38.99
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,570.00	1,200.00	370.00	23.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,082.57	2,127.05	955.52	31.00
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	3,082.57	1,700.00	1,382.57	44.85
+ GST 7.00/7.00% (S\$)	215.78	119.00	96.78	44.85
Nett Amount (S\$)	3,298.35	1,819.00	1,479.35	44.85

INSPECTION

Date of Assignment:	26/04/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	26/04/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2021)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8998B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER COVER	Repair	499.90 FL	-	*- FL
2	1		*FRONT BUMPER BRACKET LH	Serviceable	82.30 FL	-	*- FL
3	1		*FRONT FENDER LH	Deformed	945.30 FL	-	*945.30 FL
4	1		*FRONT FENDER EMBLEM	Necessary	86.50 FL	-	*86.50 FL
5	1		*FRONT WHEEL COVER LH	Scratched	189.60 FL	-	*189.60 FL
6	1		*FRONT FENDER SHIELD LH	Serviceable	198.50 FL	-	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,002.10	1,221.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	500.53	305.35
Total Parts (\$\$)	1,501.57	916.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	700.00
2	SPRAY PAINTING	New	750.00	500.00
3	CHECK WIRING & LIGHTING	New	60.00	0.00
4	RESET FRONT WHEEL ALIGNMENT	New	60.00	0.00
Gross Labour Cost (\$\$)			1,570.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >