Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)

Sent: Friday, 20 January 2023 11:52 AM

To: geraldpoh@lonpac.com
Cc: Admin A; MT_Claim_SG

Subject: [SEEK MANDATE] - Your ref: 20/21/21/VC05/024485 //LKK ref:

CC4/LPC21005123/Aps3q2 [ACCIDENT INVOLVING XE8558U(LONPAC) AND

GBE2580D(TP) ON 15/04/2021]

Attachments: LKK SURVEY REPORT & PHOTOS.pdf; PIR.pdf; TP LOD.pdf

Your ref: **20/21/21/VC05/024485** LKK ref: CC4/LPC21005123/Aps3q2

Dear Sirs/Mdm,

ACCIDENT INVOLVING XE8558U(LONPAC) AND GBE2580D(TP) ON 15/04/2021

We refer to the above matter.

We are of the view that liability is not on our driver favour as Police Investigation Result shows that our driver was being charged for Careless Driving.

We seek your approval to offer repairer "BEST SOLUTION AUTOCARE PTE LTD" at \$957.45(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 1,165.00	\$ 650.00
2. Loss of RENTAL (4days x \$100.00)	\$ 400.00	\$ 300.00 (3DAYS X \$100.00)
3. LTA/GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 1,572.45	<u>\$ 957.45</u>

Surveyor recommended 2days for repair + 1PRS =3DAYS.

Enclosed here with all the relevant documents for your perusal.

Kindly note that this inspection report dated 26/04/2021 is only for mandate purpose.

Kindly let us have your approval / instruction.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com |

HQ: Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

