niocare Pie Lid

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934 Business Reg. No.: 201626438D

6744 0777

= 6744 2377

Estimate Quotation

Quotation No	Apr 001/2021		
Date	26/4/2021		
Vehicle No	GBE2580D		
Make / Model	Hyudai Starex		

Cecilia Lonpac Insurance Bhd

To:

Address: 300, Beach Road #17-04/07, The Concourse, Singapore 199555

Qty	DESCRIPTION UNIT		Amount	
	Items			
1 pc	o/s front side mirror assy	0.6	\$	680.00
1 pc	o/s front outer window moulding	965	\$	285.00
		777	1 5352	
	Labour Charge	(()		
1	to dismantle damaged parts, panel beat, repair		\$	80.00
2	to putty and spray painting on affected area	20	\$	120.00
		80		
			S	
		Subtotal:	\$	1,165.00

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party sulvey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTOSST SOLU Authorised Signature

02 Pays. total: 852 2/5: 650