

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 055/IC/TC/HO/2021  
DATE : 24-APR-2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
S(079909)  
TEL : 63896111  
FAX : 62247175

OWNER'S NAME : NG KIM CHAN  
ADDRESS : BLK 523 ANG MO KIO AVE 5  
#08-4162  
S(560523)  
TELEPHONE NO : 90297899

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : CHINA TAIPING 3RD PARTY DIRECT  
VEHICLE NO : SKV9649E (13/10/2015)  
MODEL CODE : TDBARVWE52ED7Y408Z  
MODEL/YEAR : NISSAN ELGRAND 7 SEATER  
ENGINE NO : QR25384690L  
CHASSIS NO : JN1TBAE52E0802435  
MILEAGE : 1 KM 7522  
DATE IN : 24/04/2021  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HO YUE MENG  
ACCIDENT DATE : 22/04/2021

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV9649Z

| S/NO JOB CODE        | NATURE OF JOB                                                                         | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|---------------------------------------------------------------------------------------|-------------------|---------------------------|
| 1 FHI                | FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION | 48.00             | X                         |
| 2 SEALI              | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA                    | 100.00            | X                         |
| 3 ZZ/001             | REMOVE/INSTALL RH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTION. 280               | 560.00            | 280                       |
| 4 ZZ/002             | RESPRAY PAINT RH FRONT FENDER AND RH FRONT DOOR 230 X 2                               | 750.00            | 500                       |
| 5 ZZ/003             | TRANSFER RH FRONT DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM    | 80.00             | X                         |
| 6 ZZ/004             | TO DISCONNECT AND CONNECT VEHICLE MAIN ELECTRICAL POWER TO FACILITATE THE REPAIR      | 240.00            | X                         |
| TOTAL LABOUR CHARGES |                                                                                       | 1778.00           |                           |

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV96498

|                                                       |                                 | DAMAGED PARTS & PRICES |         |                     |
|-------------------------------------------------------|---------------------------------|------------------------|---------|---------------------|
| S/NO                                                  | PARTS DESCRIPTION               | PARTS NUMBER           | NETT    | LIST S/NETT REMARKS |
| 1                                                     | WSTRIP ASSY-FRONT DOOR,RH X NM  | 80830-1JA0C            | 150.10  |                     |
| 2                                                     | TAPE-FRONT DOOR OUTSIDE,RH X NM | 80812-1JA1A            | 19.50   |                     |
| 3                                                     | TAPE-FRONT DOOR SASH,RH X NM    | 80816-1JA0B            | 65.00   |                     |
| 4                                                     | TAPE-FRONT DOOR SASH,RH X NM    | 80818-1JA0B            | 32.50   |                     |
| 5                                                     | DOOR-FRONT RH X R               | H010M-6AXMB            | 1204.10 |                     |
| 6                                                     | FENDER-FRONT RH — PD            | 63100-1JB0B            | 706.60  |                     |
| SUB TOTAL                                             |                                 |                        | 2177.80 | 0.00 0.00           |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |                                 |                        | 435.56  | 0.00 0.00           |
| GRAND TOTAL                                           |                                 |                        | 1742.24 | 0.00 0.00           |
| OVERALL TOTAL                                         |                                 |                        | 1742.24 |                     |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV9649Z

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 1778.00   |
| TOTAL SPARE PARTS CHARGES | 1742.24   |
| GRAND TOTAL               | 3520.24 * |

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

|                 |   |      |
|-----------------|---|------|
| NAME            | : |      |
| SURVEYED DATE   | : |      |
| AUTHORIZED DATE | : |      |
| EXCESS CLAUSE   | : | 0.00 |
| LIABILITY       | : | 0.00 |
| REMARKS         | : |      |

Steve (LKK)  
7/6/21, 11:39am

Wil PL  
4/2/21  
3 1/4 hrs  
P/P  
My BL sy

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: