

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : 055/IC/TC/HO/2021
DATE : 24-APR-2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : NG KIM CHAN
ADDRESS : BLK 523 ANG MO KIO AVE 5
#08-4162
S(560523)
TELEPHONE NO : 90297899

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : CHINA TAIPING 3RD PARTY DIRECT
VEHICLE NO : SKV9649Z
MODEL CODE : TDBARVWE52ED7Y408Z
MODEL/YEAR : NISSAN ELGRAND 7 SEATER
ENGINE NO : QR25384690L
CHASSIS NO : JN1TBAE52Z0802435
MILEAGE : 75222 KM
DATE IN : 24/04/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HO YUE MENG
ACCIDENT DATE : 22/04/2021

"Finalised Bill"

To: LKK

ATTN: Steve

3 days

Best regards
YM H=

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV9649Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01W	**COMPLETE WAXING OF VEHICLE		
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	.00
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	.00
4	ZZ/001	REMOVE/INSTALL RH FRONT FENDER AND AFFECTED PORTION.REPAIR RH FRONT DOOR	560.00	280.00
5	ZZ/002	RESPRAY PAINT RH FRONT FENDER AND RH FRONT DOOR	750.00	500.00
6	ZZ/003	TRANSFER RH FRONT DOOR MECHANISM TO NEW DOOR AND CHECK DOOR CENTRAL LOCKING SYSTEM	80.00	.00
7	ZZ/004	TO DISCONNECT AND CONNECT VEHICLE MAIN ELECTRICAL POWER TO FACILITATE THE REPAIR	240.00	.00
TOTAL LABOUR CHARGES			1778.00	780.00

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV9649Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	WSTRIP ASSY-FRONT DOOR,RH	80830-1JA0C	150.10			X
2	TAPE-FRONT DOOR OUTSIDE,RH	80812-1JA1A	19.50			X
3	TAPE-FRONT DOOR SASH,RH	80816-1JA0B	65.00			X
4	TAPE-FRONT DOOR SASH,RH	80818-1JA0B	32.50			X
5	DOOR-FRONT RH	H010M-6AXMB	1204.10			X
6	FENDER-FRONT RH	63100-1JB0B	706.60			OK
SUB TOTAL			706.60	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			141.32	0.00	0.00	
GRAND TOTAL			565.28	0.00	0.00	
OVERALL TOTAL			565.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SKV9649Z

NETT ITEM	706.60
LESS 20.00%)	-141.32
NETT AMOUNT	565.28
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	0.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	0.00
TOTAL LABOUR CHARGES	780.00
TOTAL SPARE PARTS CHARGES	565.28
TOTAL CHARGES	1345.28
ADD 7 % GST	94.17
GRAND TOTAL	1439.45