

ASS. REQ. BY:

REF:

A/G / 2100 5078 / K9
2100 5174 / K9
ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fares

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Not Insured
L1 Reg &
Repairing After Rain
24 days

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 FRONT BONNET	1 PC	<i>Bu</i> 882.00	<i>✓</i>
2 FRONT BONNET HINGE LH / RH	2 PC	<i>Return</i> 96.00	<i>✓</i>
3 FRONT BONNET INSULATOR LH / RH	2 PC	<i>Return</i> 80.00	<i>✓</i>
4 FRONT BONNET CLIPS	20 PC	<i>Return</i> 70.00	<i>✓</i>
5 FRONT BONNET AIR DUCT BIG	1 PC	<i>CM</i> 56.00	<i>✓</i>
6 FRONT BONNET AIR DUCT SMALL	1 PC	<i>CM</i> 12.00	<i>✓</i>
7 FRONT BONNET INNER LOCK	1 PC	<i>DIT</i> 60.00	<i>✓</i>
8 FRONT BONNET CATCH	1 PC	<i>Return</i> 40.00	<i>✓</i>
9 FRONT BONNET GRILLE (TOP)	1 PC	<i>CM</i> 208.00	<i>✓</i>
10 FRONT BONNET EMBLEM	1 PC	<i>Return</i> 67.60	<i>✓</i>
11 FRONT BONNET BRACKET	1 PC	<i>Return</i> 15.00	<i>✓</i>
12 HEADLAMP LH / RH	2 PC	<i>Bu</i> 4,760.00	<i>✓</i>
13 HEADLAMP LOWER BEAM LH / RH 2	2 PC	<i>DIT</i> 80.00	<i>✓</i>
14 HEADLAMP WASHER NOZZLE LH / RH	2 PC	<i>Return</i> 158.40	<i>✓</i>
15 HEADLAMP WASHER NOZZLE COVER LH / RH	2 PC	<i>Return</i> 108.00	<i>✓</i>
16 HEADLAMP WASHER NOZZLE PIPE	1 PC	<i>Return</i> 64.80	<i>✓</i>
17 FRONT GRILLE (LOWER)	1 PC	<i>CM</i> 316.80	<i>✓</i>
18 FRONT GRILLE CLIPS	8 PC	<i>Return</i> 28.00	<i>✓</i>
19 FRONT BUMPER	1 PC	<i>Bu</i> 594.50	<i>✓</i>
20 FRONT BUMPER SIDE RETAINER LH / RH	2 PC	<i>DIT</i> 25.20	<i>✓</i>
21 FRONT BUMPER CLIPS	15 PC	<i>Return</i> 52.50	<i>✓</i>
22 TOWING COVER	1 PC	<i>DIT</i> 6.00	<i>✓</i>
23 FRONT BUMPER REINFORCEMENT	1 PC	<i>Bu</i> 288.00	<i>✓</i>
24 FRONT BUMPER SPONGE	1 PC	<i>Bu</i> 126.00	<i>✓</i>
25 FOGLAMP LH / RH	2 PC	<i>Return</i> 544.00	<i>✓</i>
26 FOGLAMP COVER CHROME LH / RH	2 PC	<i>Return</i> 96.00	<i>✓</i>
27 FRONT FENDER LH / RH	2 PC	<i>Bu</i> 600.00	<i>✓</i>
28 FRONT FENDER COWLING LH / RH	2 PC	<i>Return</i> 192.00	<i>✓</i>
29 FRONT FENDER COWLING CLIPS	16 PC	<i>Return</i> 56.00	<i>✓</i>
30 RADIATOR SUPPORT PANEL ASSY	1 PC	<i>Bu</i> 400.00	<i>✓</i>
31 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	<i>CM</i> 24.00	<i>✓</i>
32 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	8 PC	<i>Return</i> 28.00	<i>✓</i>
33 OIL COOLER	1 PC	<i>Return</i> 238.00	<i>✓</i>
34 OIL COOLER BRACKET - CHK PRICE	1 PC	<i>Return</i> 0.00	<i>✓</i>
35 OIL COOLER INLET HOSE	1 PC	<i>Return</i> 19.50	<i>✓</i>
36 OIL COLLER OUTLET HOSE	1 PC	<i>Return</i> 29.50	<i>✓</i>
37 AIR CON CONDENSER	1 PC	<i>Bu</i> 680.00	<i>✓</i>

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A #01-09
Singapore 568047
TEL: 6483 1244 FAX: 6483 6170 Email: ahlmmc@singnet.com.sg

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

SURVEYOR COPY

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
38 AIR CON CONDENSER FAN MOTOR ASSY	1 PC	520.00	?
39 AIR CON CONDENSER PIPE(FROM COND TO COMP)	1 PC	180.00	?
40 AIR CON CONDENSER PIPE (FRPOM COND TO VALVE)	1 PC	180.00	?
41 RADIATOR	1 PC	900.00	?
42 RADIATOR FAN MOTOR	1 PC	324.00	?
43 RADIATOR FAN BLADE	1 PC	60.00	?
44 RADIATOR FAN COWLING	1 PC	96.00	✓
45 RADIATOR SPARE TANK	1 PC	72.00	✓
46 RADIATOR TOP HOSE	1 PC	44.00	?
47 RADIATOR BOTTOM HOSE	1 PC	32.00	?
48 RADIATOR TOP BRACKET LH / RH	2 PC	32.80	x
49 RADIATOR AIR GUIDE LH / RH	2 PC	37.40	?
50 WASHER TANK	1 PC	104.00	?
51 TURBO INLET HOSE RH	1 PC	204.00	?
52 FAN BELT	1 PC	65.00	?
53 IDLER BEARING	1 PC	72.00	?
54 FRONT ENGINE MOUNTING RH	1 PC	220.00	?
55 FRONT ENGINE MOUNTING LH	1 PC	220.00	?
56 GEARBOX MOUNTING REAR	1 PC	120.00	?
57 ENGINE UNDER COVER FRONT	1 PC	320.00	x
58 ENGINE UNDER COVER CLIPS	10 PC	35.00	x
59 AIR DUCT OUTER	1 PC	56.00	?
60 AIR DUCT CLIPS	2 PC	7.00	?
61 AIR FILTER BOX HOUSING FRT	1 PC	36.00	?
62 AIR FILTER HOUSING REAR	1 PC	36.00	?
63 HORN	2 PC	115.60	?
64 TAILGATE EMBLEM	1 PC	88.00	✓
65 TAILGATE SUBARU FORESTER LOGO	1 PC	72.00	✓
66 TAILGATE XT LOGO	1 PC	72.00	✓
67 TAILGATE INNER LOCK	1 PC	560.00	x
68 TAILAMP LH / RH	2 PC	864.00	x
69 REAR BUMPER	1 PC	540.00	✓
70 REAR BUMPER SIDE RETAINERS LH / RH	2 PC	32.00	?
71 REAR BUMPER CLIPS	15 PC	52.50	✓
72 REAR BUMPER TOW COVER	1 PC	14.00	✓
73 REAR BUMPER REFLECTOR LH / RH	2 PC	45.60	x
74 REAR BUMPER REINFORCEMENT	1 PC	320.00	✓
75 REAR END PANEL	1 PC	288.00	✓

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimum@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		SS	SS
76 REAR END PANEL TOP GARNISH	1 PC	Sm 40.00	X
77 KEYLESS ANTENNA	1 PC	95.00	?
78 COMPARTMENT SPONGE CENTER	1 PC	cm 120.00	✓
79 COMPARTMENT SPONGE LH & RH	2 PC	64.80	✓
80 SPARE TYRE PANEL	1 PC	Ry 432.00	✓
81 SPARE TYRE PANEL TOP TRIM BOARD	1 PC	Sm 320.00	X
82 SPARE TYRE SPONGE TOP	1 PC	cm 36.00	✓
83 SPARE TYRE SPONGE LOWER	1 PC	cm 100.00	✓
84 TOOL BOX SPONGE - CHK PRICE	1 PC	0.00	?
85 SPARE TYRE HOLDER	1 PC	R 10.10	X
86 SPARE TYRE HOLDER SCREW	1 PC	Sm 15.10	X
87 REAR EXHAUST ASSY RH	1 PC	Ry 668.00	✓
88 REAR EXHAUST BUSH	2 PC	24.00	?
89 REAR EXHAUST GASKET	1 PC	8.00	?
90 REAR CHASSIS LH / RH	2 PC	R 708.00	X
		20,779.70	
	Less 20%	4,155.94	16,623.76
Special Nett			
91 REVERSE SENSOR	1 SET	Del 200.00	✓
92 NUMBER PLATE	1 PC	Ry 35.00	✓
93 RADIATOR COOLANT	1 PC	mc 30.00	✓
94 ATF OIL	1 PC	mc 180.00	60.00
		445.00	445.00
LABOUR			
95 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	✓
96 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	✓
97 TO REMOVE / REINSTALL ENGINE MOUNTING & GEARBOX MOUNTING	1 PC	120.00	?
98 TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC TOOL	1 PC	280.00	?
99 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
100 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT CHASSIS LH / RH, FRONT DOOR LH / RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	800.00

SURVEYOR COPY

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE
SINGAPORE 558757

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		S\$	S\$
101 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH / RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH / RH, FRONT DOOR LH / RH	1 PC	1,400.00	1200
		3,200.00	3,200.00
	Total		S\$ 20,268.76
	Add GST @ 7%		1,418.81
	Total Amount Payable		S\$ 21,687.57

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND SIX HUNDRED EIGHTY SEVEN AND CENTS FIFTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
Singapore 568047
Tel: 6483 0170
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

re:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	22/04/2021 14:28 (SGT)
Date of Accident	22/04/2021 07:30 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE AMK AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM1371L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	ANIL SINGH GURM
NRIC No	SXXXX830E
Email Address	ANILSGURM@GMAIL.COM
Mobile Phone No	(Phone) +65-97556200
Alternative Phone No	+65-92748984
VEHICLE PARTICULARS	
Manufacturer	Subaru
Model	FORESTER 2.0XT CVT AWD SR
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998


INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	P10152739R02
Cover Note Number	22/03/2021 - 21/03/2022

DRIVER

Name of Driver	SHIVNEET KAUR VIRK
NRIC No	SXXXX234H

Date of accident: 22/04/2021 Time: 7:30 Location: CTE AMK AVE 1 EKA
 My Vehicle A: SLM 1371 L Vehicle B: SKT 9367 Y Vehicle C: YN 8720 H
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling in last lane ^{on CTE} ~~to~~ between 7:25 - 7:30 when the vehicle in front of me (white lorry) jammed his brake and stopped for no apparent reason so I jammed my brake and managed to stop in time without hitting. The vehicle behind me (Jaguar) hit me from behind. It propelled my vehicle forward and into the back of the white lorry in front of me.

Veh B: Abraham Thomas / S1547749T

Veh C: Baluchamy Periyakaruppan / F8084513T

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:
 My workshop :
 Email address :
 & myself :
 Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own Insurer for more information.


DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY