



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Not Authorized
21 Days @ 13,400
Recovery After Repair
24 days

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 FRONT BONNET	1 PC	882.00	✓
2 FRONT BONNET HINGE LH / RH	2 PC	96.00	✓
3 FRONT BONNET INSULATOR LH / RH	2 PC	80.00	✓
4 FRONT BONNET CLIPS	20 PC	70.00	✓
5 FRONT BONNET AIR DUCT BIG	1 PC	56.00	✓
6 FRONT BONNET AIR DUCT SMALL	1 PC	12.00	✓
7 FRONT BONNET INNER LOCK	1 PC	60.00	✓
8 FRONT BONNET CATCH	1 PC	40.00	✓
9 FRONT BONNET GRILLE (TOP)	1 PC	208.00	✓
10 FRONT BONNET EMBLEM	1 PC	67.60	✓
11 FRONT BONNET BRACKET	1 PC	15.00	✓
12 HEADLAMP LH / RH	2 PC	4,760.00	✓
13 HEADLAMP LOWER BEAM LH / RH 2	2 PC	80.00	✓
14 HEADLAMP WASHER NOZZLE LH / RH	2 PC	158.40	✓
15 HEADLAMP WASHER NOZZLE COVER LH / RH	2 PC	108.00	✓
16 HEADLAMP WASHER NOZZLE PIPE	1 PC	64.80	✓
17 FRONT GRILLE (LOWER)	1 PC	316.80	✓
18 FRONT GRILLE CLIPS	8 PC	28.00	✓
19 FRONT BUMPER	1 PC	594.50	✓
20 FRONT BUMPER SIDE RETAINER LH / RH	2 PC	25.20	✓
21 FRONT BUMPER CLIPS	15 PC	52.50	✓
22 TOWING COVER	1 PC	6.00	✓
23 FRONT BUMPER REINFORCEMENT	1 PC	288.00	✓
24 FRONT BUMPER SPONGE	1 PC	126.00	✓
25 FOGLAMP LH / RH	2 PC	544.00	✓
26 FOGLAMP COVER CHROME LH / RH	2 PC	96.00	✓
27 FRONT FENDER LH / RH	2 PC	600.00	✓
28 FRONT FENDER COWLING LH / RH	2 PC	192.00	✓
29 FRONT FENDER COWLING CLIPS	16 PC	56.00	✓
30 RADIATOR SUPPORT PANEL ASSY	1 PC	400.00	✓
31 RADIATOR SUPPORT PANEL TOP GARNISH	1 PC	24.00	✓
32 RADIATOR SUPPORT PANEL TOP GARNISH CLIPS	8 PC	28.00	✓
33 OIL COOLER	1 PC	238.00	✓
34 OIL COOLER BRACKET - CHK PRICE	1 PC	0.00	✓
35 OIL COOLER INLET HOSE	1 PC	19.50	✓
36 OIL COLLER OUTLET HOSE	1 PC	29.50	✓
37 AIR CON CONDENSER	1 PC	680.00	✓

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : ANIL SINGH GURM
 63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 22/04/2021
 TP Veh Reg No: SKT9367Y

Estimate No: MC1901905
 Date: 23 Apr 2021
 Policy No: P10152739R02
 Veh Reg No: SLM1371L
 Make/Model: SUBARU FORESTER
 2.0XT CVT AWD SR

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		SS	SS
38 AIR CON CONDENSER FAN MOTOR ASSY	1 PC	CM 520.00	✓
39 AIR CON CONDENSER PIPE(FROM COND TO COMP)	1 PC	Sn 180.00	X
40 AIR CON CONDENSER PIPE (FRPOM COND TO VALVE)	1 PC	Sn 180.00	X
41 RADIATOR	1 PC	Bt/Pa 900.00	✓
42 RADIATOR FAN MOTOR	1 PC	Od 324.00	✓
43 RADIATOR FAN BLADE	1 PC	CM 60.00	✓
44 RADIATOR FAN COWLING	1 PC	CM 96.00	✓
45 RADIATOR SPARE TANK	1 PC	Od 72.00	✓
46 RADIATOR TOP HOSE	1 PC	At 44.00	✓
47 RADIATOR BOTTOM HOSE	1 PC	Sn 32.00	X
48 RADIATOR TOP BRACKET LH / RH	2 PC	X 32.80	X
49 RADIATOR AIR GUIDE LH / RH	2 PC	Sn 37.40	X
50 WASHER TANK	1 PC	Sn 104.00	X
51 TURBO INLET HOSE RH	1 PC	Sn 204.00	X
52 FAN BELT	1 PC	Sn 65.00	X
53 IDLER BEARING	1 PC	Sn 72.00	X
54 FRONT ENGINE MOUNTING RH	1 PC	Sn 220.00	X
55 FRONT ENGINE MOUNTING LH	1 PC	Sn 220.00	X
56 GEARBOX MOUNTING REAR	1 PC	Sn 120.00	X
57 ENGINE UNDER COVER FRONT	1 PC	R 320.00	X
58 ENGINE UNDER COVER CLIPS	10 PC	nn 35.00	X
59 AIR DUCT OUTER	1 PC	Sn 56.00	X
60 AIR DUCT CLIPS	2 PC	nn 7.00	X
61 AIR FILTER BOX HOUSING FRT	1 PC	Sn 36.00	X
62 AIR FILTER HOUSING REAR	1 PC	Sn 36.00	X
63 HORN	2 PC	Sn 115.60	X
64 TAILGATE EMBLEM	1 PC	nn 88.00	✓
65 TAILGATE SUBARU FORESTER LOGO	1 PC	nn 72.00	✓
66 TAILGATE XT LOGO	1 PC	nn 72.00	✓
67 TAILGATE INNER LOCK	1 PC	R 560.00	X
68 TAILAMP LH / RH	2 PC	Sn 864.00	X
69 REAR BUMPER	1 PC	Bu/CM 540.00	✓
70 REAR BUMPER SIDE RETAINERS LH / RH	2 PC	Sn 32.00	X
71 REAR BUMPER CLIPS	15 PC	nn 52.50	✓
72 REAR BUMPER TOW COVER	1 PC	nn 14.00	✓
73 REAR BUMPER REFLECTOR LH / RH	2 PC	Sn 45.60	X
74 REAR BUMPER REINFORCEMENT	1 PC	Bt 320.00	✓
75 REAR END PANEL	1 PC	Bt 288.00	✓

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO-06470300B

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO-06470300B

SURVEYOR COPY

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
76 REAR END PANEL TOP GARNISH	1 PC	40.00	X
77 KEYLESS ANTENNA	1 PC	95.00	X
78 COMPARTMENT SPONGE CENTER	1 PC	120.00	X
79 COMPARTMENT SPONGE LH & RH	2 PC	64.80	X
80 SPARE TYRE PANEL	1 PC	432.00	X
81 SPARE TYRE PANEL TOP TRIM BOARD	1 PC	320.00	X
82 SPARE TYRE SPONGE TOP	1 PC	36.00	X
83 SPARE TYRE SPONGE LOWER	1 PC	100.00	X
84 TOOL BOX SPONGE - CHK PRICE	1 PC	0.00	X
85 SPARE TYRE HOLDER	1 PC	10.10	X
86 SPARE TYRE HOLDER SCREW	1 PC	15.10	X
87 REAR EXHAUST ASSY RH	1 PC	668.00	X
88 REAR EXHAUST BUSH	2 PC	24.00	X
89 REAR EXHAUST GASKET	1 PC	8.00	X
90 REAR CHASSIS LH / RH	2 PC	708.00	X
		20,779.70	
	Less 20%	4,155.94	16,623.76
Special Nett			
91 REVERSE SENSOR	1 SET	200.00	X
92 NUMBER PLATE	1 PC	35.00	X
93 RADIATOR COOLANT	1 PC	30.00	X
94 ATF OIL	1 PC	180.00	X
		445.00	445.00
LABOUR			
95 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	X
96 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00	X
97 TO REMOVE / REINSTALL ENGINE MOUNTING & GEARBOX MOUNTING	1 PC	120.00	X
98 TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC TOOL	1 PC	280.00	X
99 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
100 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT CHASSIS LH / RH, FRONT DOOR LH / RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,200.00	X

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate No: MC1901905
Date: 23 Apr 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price	Amount
101 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH / RH, RADIATOR SUPPORT PANEL, FRONT CHASSIS LH / RH, FRONT DOOR LH / RH	1 PC	S\$ 1,400.00	S\$ 1,400.00
		3,200.00	3,200.00
	Total		S\$ 20,268.76
	Add GST @ 7%		1,418.81
	Total Amount Payable		S\$ 21,687.57

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND SIX HUNDRED EIGHTY SEVEN AND CENTS FIFTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

8/34 11cv

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : ANIL SINGH GURM
63 CHARTWELL DRIVE

SINGAPORE 558757

Estimate No: MC1901905
Date: 07 May 2021
Policy No: P10152739R02
Veh Reg No: SLM1371L
Make/Model: SUBARU FORESTER
2.0XT CVT AWD SR

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/04/2021
TP Veh Reg No: SKT9367Y

Estimate Repair Cost to Vehicle No :SLM1371L

Description	Quantity	List Price S\$	Amount S\$
Supplementary Parts to Repair			
SPARE PARTS			
1 FRONT BONNET CHROME UPPER	1 PC	150.40	✓
2 DUCT - BUMPER	1 PC	16.00	✓
3 RADIATOR SPONGE	1 PC	19.50	✓
4 PACKING RADIATOR	1 PC	28.70	✓
5 PACKING RADIATOR LH	1 PC	28.70	✓
6 FRONT LOWER MEMBER	1 PC	120.00	✓
7 SILENCER LH	1 PC	668.00	✓
8 STAY HOOD SUPPORT	1 PC	110.00	✓
9 REAR CENTRE SILENCER PIPE	1 PC	1,100.00	✓
10 REAR FRAME SUB ASSEMBLY	1 PC	760.00	✓
11 REAR CROSSMEMBER	1 PC	154.00	✓
		3,155.30	3,155.30
	Total		S\$ 3,155.30
	GST Amount		S\$ 220.87
	Total Amount Payable		S\$ 3,376.17

The above vehicle was surveyed by KENNETH KONG -LKK on 26/04/2021

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE 6483 6170