1 of 2?	>	ÞΙ	$\bigcirc$	$\Theta$	100%	~	<sub>G</sub>	Find   Next	



14

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En	Automob	pile						
	GREAT AMERICAN	N INSURANCE COMPANY		Ref:	CS3/GAI21005136/R1tf3						
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	AL TOWER		Date:	26/04/2021						
				Code:	GAI						
1.	Policy Particulars :- (THIRD PARTY CLAIM)										
	Insured Veh.	GBD 6640T	Veh. Inspected	l	YP 384L						
	Policy No.		Coverage (\$)		0.00						
	Claim No.	CLMOMVC000003959	Excess (\$)		0.00						
	Assign From	SHERY WONG	Assign Date		26/04/2021						
2.		Vehicle Partic	ulars & Condition	on							
	Make & Model		c.c		0						
	Engine No.	HIDDEN	Year of Reg.								
	Chassis No.		Colour								
	Odometer	-	Steering								
	Brakes		Modification								
	General										
3.		Condition	ons of Tyres								
		Size	Make		Balance						
	R/H Front Tyre				mm						
	L/H Front Tyre				mm						
	R/H Rear Tyre				mm						
	L/H Rear Tyre				mm						
4.		Descriptio	n of Damages								
5.	General Information										
	Accident Date	03/02/2021	Inspection Dat	e	27/04/2021						
	Survey held at	WILLY MOTOR COMPANY									
		27A JURONG PORT ROAD #01-32 SINGAPORE 619101									
5a.	Remarks										
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.										