

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP 401
Denise

ESTIMATE OF REPAIR

Veh# : SMV8283C

Model: MITSUBISHI LANCER

Accident Date : 25/4/2021

JmYSRCYIA

(11/8/2017)

Location : PIE TOWARDS THOMSON EXIT (ADAM FLYOVER)

3P: SKF2781D (UOI)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Delud</i>	815.00	-	-
2	8 pcs	Rear bumper clips <i>re</i>	-	24.00	-
3	1 pc	Rear bumper enforcement <i>best</i>	453.00	<i>256</i>	-
4	1 pc	Rear bumper tow cover <i>Delud</i>	56.80	-	-
5	2 pcs	Rear bumper o/s & n/s reflector <i>could</i>	167.00	-	-
6	2 pcs	Rear bumper o/s & n/s retainer <i>re</i>	129.40	<i>68</i>	-
7	1 pc	Rear reverse sensor <i>Don't</i>	-	280.00	<i>200</i>
8	1 pc	Rear tail-gate <i>Reis</i>	1,100.90	x	-
9	1 pc	Rear tail-gate inner trim	320.40	x	-
10	6 pcs	Rear tail-gate inner trim clips	-	18.00	-
11	2 pcs	Rear tail-gate o/s & n/s reflector	324.20	+	-
12	1 pc	Rear tail-gate weatherstrip	220.20	+	-
13	1 pc	Rear tail-gate lock (upper)	183.20	+	-
14	1 pc	Rear tail-gate lock (lower)	87.10	+	-
15	1 pc	Rear tail-gate 'MITSUBISHI' emblem	93.80	<i>45</i>	-
16	1 pc	Rear tail-gate 'LANCER' emblem	77.50	<i>48</i>	-
17	1 pc	Rear tail-gate 'C&C' emblem	83.20	<i>35</i>	-
18	1 pc	Rear end panel <i>Dented</i>	657.80	<i>506</i>	-
19	1 pc	Rear end panel inner trim <i>Delud</i>	162.70	-	-
20	6 pcs	Rear end panel inner trim clips <i>re</i>	-	18.00	-
21	1 pc	Rear end panel stay <i>re</i>	134.00	+	-
22	1 pc	Rear o/s tail lamp <i>could</i>	436.30	<i>356</i>	-
23	1 pc	Rear o/s fender inner trim <i>atla</i>	489.10	+	-
24	1 pc	Rear regn. no. plate <i>could</i>	-	45.00	<i>30</i>
25	1 pc	Rear regn. no. plate bracket <i>Delud</i>	-	29.00	-
Sub-Total:			5,991.60	414.00	0.00
			10%	0%	0%
After Less %:			5,392.44	414.00	0.00

List: 2515.50

len 10%: 226395

S.N: 301

		Labour	
1		To dismant and repair rear damaged parts.	1,200.00 <i>600</i>
2		To spray painting.	800.00 <i>600</i>
3		To check wiring.	50.00 <i>30</i>
4		To re-seal anti-rust.	80.00 <i>60</i>
		Sub-Total:	2,130.00
		Total:	7,936.44
		After Less 20%:	6,349.15

llan

1290

Chan San Choon
Director

DipEng, AAE MIMI,MSAE(Aust)



8778 1999
24 hr accident call

Mobil 1



Adrian G

26/04/21.

r/s. 05 days.

total: 3854.55

r/s: 3050.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: