

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/XD6306Z/TPC

AIG Asia Pacific Insurance Pte Ltd

CHARTIS Building

78 Shenton Way

#07-16

Singapore 079120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION

Dear Sir,

Cost of Repair to Vehicle XD6306Z

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Foot step plate LH / CA	1	185.00	185.00
2.	Foot step plate bracket LH X Repair	1	355.00	355.00
3.	Foot step housing LH ✓ CA	1	750.00	750.00
4.	Front LH headlamp housing / CA	1	760.00	760.00
5.	Front LH side garnish (behind headlamp housing) CA	1	345.00	345.00
6.	LH side small lamp ✓ CA	1	103.00	103.00
7.	Remove & refit front sensors	1	80.00	80.00
8.	Check wiring	1	20.00	20.00
9.	Labour charges	1	600.00	600.00
SUB-TOTAL				S\$3,198.00

- Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai
HP: 9850-9666



2 Days .

Unpsum repair

After repair photos

Gmo Qian - 82880282

28/4/21